

DATE: 02/16/2006
 Time: 12:18 p.m.

WILATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-422/ROV PAGE: 1
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C IJMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTZ	PRICE/WG	TOTAL COST
0001-0017879	5	L 010603	021-000-000	N/A	DESTINATION SIGNS	RPR 0006	0.3	28.160	8.448
0001-0017879	5	note			FRONT LIGHT IN SIDE DESTINATION SIGN IS OUT		**		
0001-0017879	1	L 011003	010-400-000	N/A	LOAD:ALARM,BULB,BUZZ	RPR 0006	0.5	28.160	14.080
0001-0017879	1	note			Horn doesn't work		**		
0001-0017879	1	note			REPAIRED WIRING AT HORNS, REMOUNTED (1) HORN TO PREVENT IT		**		
0001-0017879	1	note			FROM FILLING WITH WATER		**		
0001-0017879	2	L 011003	015-100-000	N/A	EXTERIOR MIRRORS	RPL 0006	0.5	28.160	14.080
0001-0017879	2	note			LH mirror is broken		**		
0001-0017879	2	note			REPLACED MIRROR HEAD		**		
0001-0017879	3	L 011003	016-100-000	N/A	INTERIOR	RPR 0006	0.5	28.160	14.080
0001-0017879	3	note			Pass. stop request cable is broken on LH side		**		
0001-0017879	3	note			RE-ATTACHED CABLE TO WLL MOUNT		**		
0001-0017879	2	P 011403	015-100-000	TML	TROLLEY MIRROR LEFT (FLA RPL N/A	N/A	1.0	20.000	20.000
0001-0017879	2	note			LH mirror is broken		**		
0001-0017879	2	note			REPLACED MIRROR HEAD		**		
0001-0017921	1	L 011503	022-000-000	N/A	WHEELCHAIR LIFTS	RC 0012	2.5	28.160	70.400
0001-0017921	1	P 011503	022-000-000	25100	SOCKET,LAMP DASH (168/19 RC N/A	N/A	2.0	1.060	2.120
0001-0017921	1	note			ROAD CALL TO LYNDEN - WHEEL CHAIR LIFT IN-OP		**		
0001-0017921	1	note			LIFT LOCK WAS STUCK, NOT ALLOWING LIFT TO DEPLOY		**		
0001-0017921	1	note			CLEAR LOCK, VERIFY OPERATION		**		
0001-0017921	2	L 011503	010-360-000	N/A	LIGHTS-INTERIOR	RPR 0012	0.5	28.160	14.080
0001-0017921	2	note			SPEEDO LIGHT IN-OP		**		
0001-0017921	2	note			CLEARANCE LIGHT IN-OP		**		
0001-0017952	1	L 011703	015-000-000	N/A	EXTERIOR BODY	RPR 0006	1.0	28.160	28.160
0001-0017952	1	P 012003	015-000-000	GL1905032-900	MIRROR,FLAT,HEATED 12V	RPR N/A	1.0	20.230	20.230
0001-0017952	1	note			LH & RH mirrors need to be switched around		**		
0001-0017952	1	note			REPLACED L/H MIRROR GLASS WITH PROPER ONE, R/H MIRROR IS		**		
0001-0017952	1	note			CORRECT		**		
0001-0018397	1	OP 022703	015-000-000	SHAWMANEE	WOODWORKING REPAIRS	OUT N/A	1.0	4099.870	4099.870
0001-0018397	1	OP 022703	015-000-000	LOPEZ	WOOD WORKING REPAIRS	OUT N/A	1.0	746.000	746.000
0001-0018397	1	OP 022703	015-000-000	DOCKSIDE	WOOD WORKING REPAIRS	OUT N/A	2.0	130.010	130.010
0001-0018397	1	OP 022703	015-000-000	LFS	WOOD WORKING PRODUCTS	OUT N/A	1.0	88.040	88.040
0001-0018397	1	note			WOOD WORKING REPAIRS BY SHAWMANEE		**		
0001-0018544	1	L 031803	025-200-000	N/A	PM B (6,000 & 12,000	PM 0016	4.5	35.000	157.500
0001-0018544	1	L 031803	025-200-000	N/A	PM B (6,000 & 12,000	PM 0016	2.0	35.000	70.000
0001-0018544	2	P 031803	025-200-000	5191640	BLADE,WIPER DYNA FOR TRO	EM N/A	2.0	11.770	23.540

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 2
 Veh: 0001-809

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTEB41WE524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47G30C Tr Miles > 244316.0

WO#	LN	TRN TYP DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/OTY	PRICE/WG	TOTAL COST
0001-0018544	1	P 031803	025-200-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM N/A	1.0	7.500	7.50
0001-0018544	1	P 031803	025-200-000	LF3000	FILTER,OIL CUMMINS	PM N/A	1.0	16.402	16.40
0001-0018544	1	P 031803	025-200-000	FS1251	FILTER,FUEL TROLLEY	PM N/A	1.0	5.863	5.86
0001-0018544	1	P 031803	025-200-000	FS1000	FILTER,FUEL USE FOR ORIO	PM N/A	1.0	7.306	7.30
0001-0018544	1	P 031803	025-200-000	80445R1	MOUNT,BODY TROLLEY	PM N/A	1.0	6.500	6.50
0001-0018544	1	P 031803	025-200-000	15W-40L	OIL,LUBEROOM TANK ONLY!!	PM N/A	25.0	0.745	18.62
0001-0018544	1	note		PM B & Webasto PM			**		
0001-0018544	1	note		REPLACED AIR FILTER			**		
0001-0018275	1	L 031903	015-200-000	N/A	BODY REPAIR/INCIDENT	RPR 0006	0.5	35.000	17.50
0001-0018275	1	note		Remove (5) front and (1) LH rear top clearance light assys.			**		
0001-0018275	1	note		for woodwork repairs.			**		
0001-0018544	1	L 031903	025-200-000	N/A	PM B (6,000 & 12,000	PM 0016	4.5	35.000	157.50
0001-0018544	1	L 031903	025-200-000	N/A	PM B (6,000 & 12,000	PM 0009	3.0	35.000	105.00
0001-0018544	1	L 031903	025-200-000	N/A	PM B (6,000 & 12,000	PM 0013	0.8	35.000	28.00
0001-0018544	1	P 031903	025-200-000	5C438	FILTER,HEATER TROLLEY	PM N/A	1.0	5.330	5.33
0001-0018544	1	P 031903	025-200-000	AH1J04	FILTER,AIR ASSY TROLLEY	PM N/A	1.0	64.370	64.37
0001-0018544	1	P 031903	025-200-000	69867	NIPPLE,BRASS 1/8" X 2"	PM N/A	1.0	0.474	0.47
0001-0018544	1	P 031903	025-200-000	69835	FITT,BRASS PIPE COUPLING	PM N/A	1.0	0.252	0.25
0001-0018544	1	P 031903	025-200-000	69880	FITT,BRASS STR EL 1/8	PM N/A	1.0	0.440	0.44
0001-0018544	1	note		PM B & Webasto PM			**		
0001-0018544	1	note		REPLACED AIR FILTER			**		
0001-0018544	4	L 031903	010-360-000	N/A	LIGHTS-INTERIOR	RPR 0013	0.2	35.000	7.00
0001-0018544	4	note		REPLACED DOOR LIGHTS			**		
0001-0018544	4	note		INTERIOR LITES DASH			**		
0001-0018544	4	note		REAR DOOR BRAKE LIGHT			**		
0001-0018544	6	L 031903	003-000-000	N/A	SUSPENSION SYSTEM	RPR 0013	2.5	35.000	87.50
0001-0018544	6	note		REAR LUBE FITTING BROKEN			**		
0001-0018544	6	note		DRILLED OUT AND TAPED S-CAM HOUSING TO REMOVE BROEKN LUBE			**		
0001-0018544	6	note		FITTING, INSTALLED NEW FITTING AND EXTENSION			**		
0001-0018544	7	L 031903	013-100-000	N/A	WEBASTO HEATER	PM 0013	2.5	35.000	87.50
0001-0018544	7	note		WEBASTO PM			**		
0001-0018544	8	L 031903	018-000-000	N/A	DOORS & REMOVABLE PA	RPR 0013	1.0	35.000	35.00
0001-0018544	8	note		REAR DOOR ROD - BROKEN HNGE			**		
0001-0018544	8	note		REPLACED BALL DRILLED OUT OLD PART TAPED-WELDED IN NEW PART			**		
0001-0018544	9	L 031903	010-100-000	N/A	BATTERY	RPR 0013	1.5	35.000	52.50
0001-0018544	9	note		MODIFY FUDL AND BATTERY DOORS			**		

DATE: 02/16/2006
 time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROV PAGE: 3
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE041WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic.Plate > 47630C LIMiles > 244316.0

WO#	LN	TRM TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0018544	1	P	032003	025-200-000	9416X83	STUD,BALL 13MM,CABLE CAR	PM	N/A	1.0	1.280	1.280
0001-0018544	1	P	032003	025-200-000	52852-3	LAMP,SEALED MODEL 60	PM	N/A	1.0	5.638	5.638
0001-0018544	1	P	032003	025-200-000	274.313	TIP,IGNITOR ELECTRODE	PM	N/A	2.0	2.398	4.796
0001-0018544	1	P	032003	025-200-000	604.902	CONTROL,THERMOSTAT	PM	N/A	1.0	25.033	25.033
0001-0018544	1	P	032003	025-200-000	886-41A	NOZZLE,0.35 60 DEGREE	PM	N/A	1.0	10.099	10.099
0001-0018544	1	P	032003	025-200-000	BF932	FILTER,WEBASTO ORION	PM	N/A	1.0	1.079	1.079
0001-0018544	1	P	032003	025-200-000	0027501	DECAL,"EMERGENCY EXIT"	PM	N/A	1.0	0.947	0.947
0001-0018544	1	P	032003	025-200-000	051845404	HINGE ASSEMBLY,FUEL DOOR	PM	N/A	2.0	15.480	30.960
0001-0018544	1	P	032003	025-200-000	011845002	SPRING,FUEL DOOR	PM	N/A	2.0	4.447	8.894
0001-0018544	1	P	032003	025-200-000	55037	SWITCH,ENGINE SPST NOM.	PM	N/A	1.0	4.220	4.220
0001-0018544	1	note			PM B & Webasto PM			**			
0001-0018544	1	note			REPLACED AIR FILTER			**			
0001-0018544	2	L	032003	022-000-000	N/A	WHEELCHAIR LIFTS	RPR	0013	3.0	35.000	105.000
0001-0018544	2	note			Replace bushings in WCL arms			**			
0001-0018544	3	L	032003	012-000-000	N/A	AIR SYSTEM	CHK	0013	1.0	35.000	35.000
0001-0018544	3	note			AIR LEAK REAR			**			
0001-0018544	3	note			REPAIRED VALVE R-14			**			
0001-0018544	4	L	032003	010-360-000	N/A	LIGHTS-INTERIOR	RPR	0013	0.5	35.000	17.500
0001-0018544	4	note			REPLACED DOOR LIGHTS			**			
0001-0018544	4	note			INTERIOR LITES DASH			**			
0001-0018544	4	note			REAR DOOR BRAKE LIGHT			**			
0001-0018544	5	L	032003	015-150-000	N/A	WIPER BLADES AND WAS	RPR	0017	1.0	35.000	35.000
0001-0018544	5	note			W/S WIPER BLADES			**			
0001-0018544	1	P	032103	025-200-000	19576	BEARING,BUSHING RICON	PM	N/A	2.0	27.500	55.000
0001-0018544	1	P	032103	025-200-000	C-075	COLLAR,SHAFT 3/4" ID	PM	N/A	2.0	1.130	2.260
0001-0018544	1	note			PM B & Webasto PM			**			
0001-0018544	1	note			REPLACED AIR FILTER			**			
0001-0018544	2	P	032103	022-000-000	F9-0089	PIN,LIFT RICON	RPR	N/A	1.0	15.230	15.230
0001-0018544	2	note			Replace bushings in WCL arms			**			
0001-0018597	1	L	032103	010-360-000	N/A	LIGHTS-INTERIOR	OTH	0012	3.0	35.000	105.000
0001-0018597	1	P	032103	010-360-000	80351	LAMP,LIGHT DOME 61W.	OTH	N/A	1.0	8.540	8.540
0001-0018597	1	note			Install rear stepwell light.			**			
0001-0018597	2	L	032103	016-000-000	N/A	INTERIOR PANELS & SP	RPR	0012	3.0	35.000	105.000
0001-0018597	2	note			Several stanchions are loose and rattle.			**			
0001-0018597	2	note			TIGHTEN STATION BARS AS NEEDED			**			
0001-0018730	1	P	040303	007-000-000	80445R1	MOUNT,BODY TROLLEY	OTH	N/A	1.0	6.500	6.500

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

IC: 3-412/ROV PAGE: 4
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841W1524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QUY	PRICE/WG	TOTAL COST
0001-0018730	1	note			RETURN BODY MOUNT PARTS NOT USED ON WORK ORDER 18544				**		
0001-0018730	1	note			WAITING FOR BODY PARTS ON ORDER				**		
0001-0018761	1	L	040703	015-150-000	N/A	WIPER BLADES AND WAS	RPL	0015	0.5	35.000	17.500
0001-0018761	1	note			Replace LH wiper blade				**		
0001-0018761	2	L	040703	020-100-000	N/A	DRIVER SEAT	CHK	0015	0.3	35.000	10.500
0001-0018761	2	note			Lower lumbar adjustments don't seem to be working correctly				**		
0001-0018761	2	note			COULD NOT DUPLICATE				**		
0001-0018761	1	P	040803	015-150-000	5191640	BLADE,WIPER DYNA FOR TRO RPL	N/A		1.0	11.770	11.770
0001-0018761	1	note			Replace LH wiper blade				**		
0001-0018761	3	L	040903	018-000-000	N/A	DOORS & REMOVABLE PA	CHK	0016	0.5	35.000	17.500
0001-0018761	3	note			Rear doors close too slowly				**		
0001-0018784	1	L	040903	013-000-000	N/A	HEATING/AIR CONDITIO	RPR	0009	1.5	35.000	52.500
0001-0018784	1	P	041003	013-000-000	92210	CLAMP,HOSE SILICONE 9/16 RPR	N/A		2.0	0.973	1.946
0001-0018784	1	note			RH rear heater is leaking coolant on to floor of coach				**		
0001-0018784	1	note			HEATER HAS BEEN KICKED - REMOUNTED AND SHORTENED LOWER HOSE				**		
0001-0018784	1	note			AND REROUTED				**		
0001-0018730	1	L	041203	007-000-000	N/A	ENGINE SYSTEM	OTH	0009	0.5	35.000	17.500
0001-0018730	1	note			RETURN BODY MOUNT PARTS NOT USED ON WORK ORDER 18544				**		
0001-0018730	1	note			WAITING FOR BODY PARTS ON ORDER				**		
0001-0018730	2	L	041203	019-000-000	N/A	WINDOWS/GLASS	RPR	0004	6.0	35.000	210.000
0001-0018730	2	note			W/S LEAKS COMPLAINT				**		
0001-0018730	2	note			REMOVED WOOD TRIM ON DRIVER'S SECTION, CLEANED OLD CAULK,				**		
0001-0018730	2	note			RECAULKED WITH BLACK SIKAFLEX-REPLACED TRIM				**		
0001-0018730	2	note			LEAK TESTED CENTER & R SECTIONS,				**		
0001-0018730	1	L	041403	007-000-000	N/A	ENGINE SYSTEM	OTH	0016	4.5	35.000	157.500
0001-0018730	1	note			RETURN BODY MOUNT PARTS NOT USED ON WORK ORDER 18544				**		
0001-0018730	1	note			WAITING FOR BODY PARTS ON ORDER				**		
0001-0018730	2	P	041403	019-000-000	221-243	SIKAFLEX,BLACK - TUBE	RPR	N/A	1.0	5.990	5.990
0001-0018730	2	note			W/S LEAKS COMPLAINT				**		
0001-0018730	2	note			REMOVED WOOD TRIM ON DRIVER'S SECTION, CLEANED OLD CAULK,				**		
0001-0018730	2	note			RECAULKED WITH BLACK SIKAFLEX-REPLACED TRIM				**		
0001-0018730	2	note			LEAK TESTED CENTER & R SECTIONS,				**		
0001-0018826	1	L	041503	022-000-000	N/A	WHEELCHAIR LIFTS	RPR	0015	7.0	35.000	35.000
0001-0018826	1	note			WCL would not stow, had to push it in manually				**		
0001-0018826	1	note			REPLACE PIN SHEARED				**		
0001-0018873	1	L	042103	012-000-000	N/A	AIR SYSTEM	CHK	0012	1.0	35.000	35.000

DATE: 02/16/2006
 Time: 12:18 p.m.

WILATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROY PAGE: 5
 Vch: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VIE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAB Lic. Plate > 47630C TrMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0018873	1	L 042103	012-000-000	N/A	AIR SYSTEM	CHK 0013	4.0	35.000	140.00
0001-0018873	1	L 042103	012-000-000	N/A	AIR SYSTEM	CHK 0013	2.0	35.000	70.00
0001-0018873	1	P 042103	012-000-000	6240605	VALVE,LEVELLING TROLLEY/	CHK N/A	2.0	52.885	105.77
0001-0018873	1	P 042103	012-000-000	225B-60ICAAA	VALVE,ELECTRIC/AIR	CHK N/A	1.0	42.120	42.12
0001-0018873	1	P 042203	012-000-000	6240605	VALVE,LEVELLING TROLLEY/	CHK N/A	1.0-	52.885	52.88
0001-0018873	1	note		BUS WAS LISTING TO THE RIGHT SIDE (AIRBAG)			**		
0001-0018873	1	note		THEN BUS WENT OVER A BUMP IT CAME BACK UP TO ALMOST REGULAR			**		
0001-0018873	1	note		HEIGHT			**		
0001-0018873	1	note		CHECK OUT PROBLEM-REPLACED LEVELING VALVE RIGHT			**		
0001-0018873	1	note		REAR-REPLACED MAC VALVE REAR LEAKING			**		
0001-0018873	2	L 042503	005-000-000	N/A	BRAKE SYSTEM	CHK 0014	0.5	35.000	17.50
0001-0018873	2	note		BRAKES WERE NOISY @ START OF SHIT GOT PROGRESSIVELY LOUDER			**		
0001-0018924	1	L 043003	025-400-000	N/A	PM D - ORION (24,000	PM 0009	8.0	35.000	280.00
0001-0018924	1	P 043003	025-400-000	15W-40L	OIL,LOBEROOM TANK ONLY!!	PM N/A	25.0	0.740	18.50
0001-0018924	1	P 043003	025-400-000	ATF	OIL,AUTOMATIC TRANSMISSI	PM N/A	17.0	0.835	14.19
0001-0018924	1	P 043003	025-400-000	80W-90	OIL,GEAR LOBE 410J DRUM	PM N/A	15.5	0.984	15.25
0001-0018924	1	P 043003	025-400-000	LF3000	FILTER,OIL CUMMINS	PM N/A	1.0	17.559	17.55
0001-0018924	1	P 043003	025-400-000	FS1000	FILTER,FUEL USE FOR ORIO	PM N/A	1.0	7.878	7.81
0001-0018924	1	P 043003	025-400-000	FS1251	FILTER,FUEL TROLLEY	PM N/A	1.0	5.863	5.86
0001-0018924	1	P 043003	025-400-000	29540493	FILTER,TRANS ALLISON	PM N/A	1.0	86.393	86.39
0001-0018924	1	P 043003	025-400-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM N/A	1.0	7.500	7.50
0001-0018924	1	P 043003	025-400-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM N/A	1.0	7.500	7.50
0001-0018984	2	L 050103	025-400-000	N/A	PM D - ORION (24,000	PM 0008	2.0	35.000	70.00
0001-0018984	2	L 050103	025-400-000	N/A	PM D - ORION (24,000	PM 0009	4.0	35.000	140.00
0001-0018984	2	P 050103	025-400-000	115-007	END,THROTTLE ROD TROLLEY	PM N/A	1.0	7.120	7.12
0001-0018984	2	P 050103	025-400-000	9311-NOT	END,ROD .25-28THR TROLLE	PM N/A	1.0	9.390	9.39
0001-0018984	2	note		FROM WO 18924			**		
0001-0018984	5	L 050103	024-400-000	N/A	TIRE REPLACE/REAR/NE	RPL 0009	1.0	35.000	35.00
0001-0018984	5	P 050103	024-400-000	TIRE	TIRE	RPL N/A	2.0	516.730	1033.46
0001-0018984	5	note		INSTALLED 2 NEW TIRES ON FRONT OF BUS			**		
0001-0018984	5	note		TORQUES ALL 4 CORNERS			**		
0001-0018984	6	L 050103	008-000-000	N/A	COOLING SYSTEM	RPL 0009	2.0	35.000	70.00
0001-0018984	6	P 050103	008-000-000	ANTIFREEZE	COOLANT,EXTEND SERV. PRE	RPL N/A	48.0	1.021	49.00
0001-0018984	6	note		COOLANT FLUSH			**		
0001-0018984	6	note		ES ANTIFREEZE			**		
0001-0018984	2	L 050203	025-400-000	N/A	PM D - ORION (24,000	PM 0008	3.0	35.000	105.00

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 6
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WB524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRM TYP	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0018984	2	L	050203	025-400-000	N/A	PM D - ORION (24,000	PM	0009	4.0	35.000	140.000
0001-0018984	2	P	050203	025-400-000	5004338	VALVE,PURGE ASSY. W/HTR	PM	N/A	1.0	118.272	118.272
0001-0018984	2	P	050203	025-400-000	107794X	CARTRIDGE,AIR DRYER AD9	PM	N/A	1.0	31.168	31.168
0001-0018984	2	P	050203	025-400-000	H6024	LAMP,HEAD TROLLEY	PM	N/A	1.0	8.287	8.287
0001-0018984	2	P	050203	025-400-000	68612	FITT,BRASS PIPE HX PLUG	UM	N/A	1.0	0.198	0.198
0001-0018984	2	P	050203	025-400-000	H6024	LAMP,HEAD TROLLEY	PM	N/A	1.0	8.287	8.287
0001-0018984	2	P	050203	025-400-000	H5024	LAMP,HEADLIGHT TROLLEY	PM	N/A	1.0	11.770	11.770
0001-0018984	2	P	050203	025-400-000	WF2121	FILTER,EXTEND SERV TIME	UM	N/A	1.0	37.280	37.280
0001-0018984	2	P	050203	025-400-000	HBR011	BRACKET,HANDRAIL TROLLEY	PM	N/A	2.0	16.500	33.000
0001-0018984	2	note			FROM WO 18924				**		
0001-0018984	6	L	050203	008-000-000	N/A	COOLING SYSTEM	RPL	0008	2.0	35.000	70.000
0001-0018984	6	L	050303	008-000-000	N/A	COOLING SYSTEM	RPL	0009	1.0	35.000	35.000
0001-0018984	6	note			COOLANT FLUSH				**		
0001-0018984	6	note			ES ANTIFREEZE				**		
0001-0018984	2	P	050503	025-400-000	6240605	VALVE,LEVELLING TROLLEY/	PM	N/A	1.0	52.885	52.885
0001-0018984	2	note			FROM WO 18924				**		
0001-0018984	3	L	050503	021-000-000	N/A	FARE BOXES	PM	0011	1.0	35.000	35.000
0001-0018984	3	L	050503	021-000-000	N/A	FARE BOXES	PM	0011	1.5	35.000	52.500
0001-0018984	3	note			BLUE DOT INSPECTION				**		
0001-0018984	6	L	050503	008-000-000	N/A	COOLING SYSTEM	RPL	0015	1.0	35.000	35.000
0001-0018984	6	note			COOLANT FLUSH				**		
0001-0018984	6	note			ES ANTIFREEZE				**		
0001-0018984	2	P	050603	025-400-000	TMR	TROLLEY MIRROR RIGHT (CO	PM	N/A	1.0	20.000	20.000
0001-0018984	2	P	050603	025-400-000	53252	LAMP,RED 10 LED S/T/T GR	PM	N/A	2.0	26.000	52.000
0001-0018984	2	P	050603	025-400-000	9416K87	SOCKET,METAL BALL (CABLE	PM	N/A	4.0	3.390	13.560
0001-0018984	2	P	050603	025-400-000	9416K213	SHOCK,COMP.ENGINE (CABLE	PM	N/A	2.0	16.790	33.580
0001-0018984	2	note			FROM WO 18924				**		
0001-0018984	4	L	050603	007-000-000	N/A	ENGINE SYSTEM	RPR	0017	2.0	35.000	70.000
0001-0018984	4	note			THROTTLE LINKAGE LOOSE				**		
0001-0018984	4	note			REPLACED ENDS AND ADJUST				**		
0001-0018984	7	L	050603	019-000-000	N/A	WINDOWS/GLASS	RPR	0017	2.0	35.000	70.000
0001-0018984	7	note			INSTALLED DRIVER'S SIDE WINDOW				**		
0001-0019091	1	L	051303	016-100-000	N/A	INTERIOR	RPR	0008	0.5	35.000	17.500
0001-0019091	1	note			Compartment door above front exit drops open (loose latch)				**		
0001-0019091	1	note			SILICONE LATCH CLOSED				**		
0001-0019136	1	L	052003	007-000-000	N/A	ENGINE SYSTEM	RPR	0006	0.5	35.000	17.500

DATE: 02/16/2006
 Time: 12:18 p.m.

MIATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROV PAGE: 7
 Veh: 0001-808

Year > 1997 Make > TRCLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LHMiles > 244316.0

NOI	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0019136	1	P 052003	007-000-000	ANTIFREEZER	COOLANT, EXTEND SERV. PRE RPR	N/A	12.0	1.021	12.25
0001-0019136	1	note			Engine dies after idling a short time		**		
0001-0019136	1	note			FILLED COOLING SYSTEM, RE-INSTALLED MISSING RADIATOR CAP		**		
0001-0019136	1	note			(FOUND IN PARKING LOT)		**		
0001-0019147	1	L 052103	019-000-000	N/A	WINDOWS/GLASS	CHK 0015	1.5	35.000	52.50
0001-0019147	1	P 052103	019-000-000	CFW500	CHANNEL, SLIDER DRIVERS T	CHK N/A	4.0	2.000	8.00
0001-0019147	1	note			install new window slide glides.		**		
0001-0019091	2	L 052303	007-000-000	N/A	ENGINE SYSTEM	RPR 0014	0.5	35.000	17.50
0001-0019091	2	note			PIN THAT THE THROTTLE PEDAL ROTATES ON HAS LOST ITS CLIP		**		
0001-0019091	2	note			REPAIRED		**		
0001-0019091	3	L 052803	010-250-000	N/A	HEADLIGHT ASSEMBLY	RPL 0013	0.3	35.000	10.50
0001-0019091	3	note			LEFT FRONT HEADLIGHT OUT		**		
0001-0019091	3	note			REPLACED		**		
0001-0019297	3	P 060303	010-350-000	N/A	LIGHTS/CLEARANCE, SKI	RPR 0013	0.5	35.000	17.50
0001-0019297	3	note			TWO CLEARANCE LIGHTS OUT JUMP SEAT BEHIND DRIVER		**		
0001-0019297	1	L 060403	026-250-000	N/A	ROAD CALL	RC 0009	1.0	35.000	35.00
0001-0019297	1	note			ROAD CALL TO TERMINAL BACK DOOR NOT CLOSING		**		
0001-0019297	2	L 060403	018-000-000	N/A	DOORS & REMOVABLE PA	CHK 0012	4.0	35.000	140.00
0001-0019297	2	P 060403	018-000-000	59320139-03	SOLENOID, AIR/ELECTRIC 12	CHK N/A	1.0	56.960	56.96
0001-0019297	2	note			BACK DOOR WILL NOT CLOSE OR IT WILL CLOSE BUT IT TAKES		**		
0001-0019297	2	note			SEVERAL MINUTES TO DO SO		**		
0001-0019297	2	note			REPLACED MAG VALVE		**		
0001-0019523	1	L 062703	010-350-000	N/A	LIGHTS/CLEARANCE, SKI	CHK 0017	1.0	35.000	35.00
0001-0019523	1	note			Operator reports: Right front marker light out.		**		
0001-0019523	1	note			REWired LIGHT		**		
0001-0019534	1	OP 063003	015-200-000	SHAWWANEE	SAND AND SEAL TOP	OUT N/A	1.0	2705.000	2705.00
0001-0019534	1	OP 063003	015-200-000	HARDWARE SALE	SANDPAPER	OUT N/A	1.0	35.070	35.07
0001-0019534	1	note			OUTSIDE REPAIR BY SHAWWANEE		**		
0001-0019534	1	note			INVOICE FROM HARDWARE SALES		**		
0001-0019543	1	L 063003	001-300-000	N/A	DRUMS, HUBS, WHEELS	CHK 0013	1.0	35.000	35.00
0001-0019543	1	P 063003	001-300-000	2208N430	GASKET, FRONT AXLE CAP-TR	CHK N/A	1.0	1.610	1.61
0001-0019543	1	note			Check front hubs for proper grease.		**		
0001-0019543	1	note			CHECKED OK FOR GREASE NEW TYPE		**		
0001-0019543	2	L 063003	015-000-000	N/A	EXTERIOR BODY	CHK 0013	1.0	35.000	35.00
0001-0019543	2	note			Operator reports: Water leak at bell pull cord.		**		
0001-0019543	2	note			RESEALED TOP LARGE HOLE BELL PULL CORD AREA		**		

DATE: 02/16/2006
 time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RET by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 8
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > IC9VTE641WB524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47E30C LfMiles > 244316.0

WO#	LN	TRN TRN TRN	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0019527	1	L	070203	025-200-000	N/A	PM B (6,000 & 12,000	PM	0008	2.0	35.000	70.00
0001-0019527	1	L	070203	025-200-000	N/A	PM B (6,000 & 12,000	PM	0013	8.0	35.000	280.00
0001-0019527	1	P	070203	025-200-000	PMB98CC	KIT-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.00
0001-0019527	1	P	070203	025-200-000	FS1000	FILTER,FUEL USE FOR ORIO	PM	N/A	1.0	7.968	7.96
0001-0019527	1	P	070203	025-200-000	FS1251	FILTER,FUEL TROLLEY	PM	N/A	1.0	6.388	6.38
0001-0019527	1	P	070203	025-200-000	LF3000	FILTER,OIL CUMMINS	PM	N/A	1.0	17.832	17.83
0001-0019527	1	P	070203	025-200-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM	N/A	1.0	7.500	7.50
0001-0019527	1	P	070203	025-200-000	3920773	WASHER,SEALING TROLLEY O	PM	N/A	1.0	0.743	0.74
0001-0019527	1	P	070203	025-200-000	5C438	FILTER,HEATER TROLLY	PM	N/A	1.0	5.330	5.33
0001-0019527	1	P	070203	025-200-000	PMB98CC	END-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.00
0001-0019527	1	P	070203	025-200-000	5C438	FILTER,HEATER TROLLY	PM	N/A	1.0	5.330	5.33
0001-0019527	1	P	070203	025-200-000	15W-40L	OIL,LUBEROOM TANK ONLY!!	PM	N/A	25.0	0.790	19.75
0001-0019527	1	P	070303	025-200-000	7792	SWITCH,FLOOR T/S	UM	N/A	1.0	19.684	19.68
0001-0019527	2	L	070303	012-100-000	N/A	AIR COMPRESSOR TEST	CHK	0008	0.5	15.000	17.50
0001-0019527	2	note			AIR COMPRESSOR TEST - VERY GOOD				**		
0001-0019527	3	L	070303	008-100-000	N/A	RADIATOR SYSTEM	RER	0008	2.0	35.000	70.00
0001-0019527	3	note			CLEASN RADIATOR				**		
0001-0019527	4	L	070303	010-000-000	N/A	ELECTRICAL/INSTRMNT	CHK	0008	1.0	35.000	35.00
0001-0019527	4	note			CHECK WIRING FOR SHORT - REPLACE T/S SW				**		
0001-0019527	5	L	070303	007-000-000	N/A	ENGINE SYSTEM	CHK	0008	1.0	35.000	35.00
0001-0019527	5	note			CHECK ENGINE DIES WHEN STOPPING - SOLENOID WEAK				**		
0001-0019589	1	L	070703	010-650-000	N/A	RADIO/ANTENNA	CHK	0011	0.5	35.000	17.50
0001-0019589	1	L	070703	010-650-000	N/A	RADIO/ANTENNA	CHK	0017	2.5	35.000	87.50
0001-0019589	1	note			Operator reports: Wierd electrical problem, apply J.C.C.				**		
0001-0019589	1	note			with front door open and am radio goes off. Turn radio off				**		
0001-0019589	1	note			and front doors close, turn radio back on and front doors				**		
0001-0019589	1	note			open, then transmission selector looses one of the N's, the				**		
0001-0019589	1	note			check trans. light comes on and you can't select any gears.				**		
0001-0019583	1	L	070803	011-000-000	N/A	HYDRAULIC SYSTEM	RPL	0016	3.5	35.000	122.50
0001-0019583	1	P	070803	011-000-000	C8019002	POMP,HYD P/S TROLLEY	RPL	N/A	1.0	766.850	766.85
0001-0019583	1	P	070803	011-000-000	154916	GASKET,PUMP	RPL	N/A	1.0	1.796	1.79
0001-0019583	1	P	070903	011-000-000	C8016552	FILTER,HYDRAULIC,STEERIN	RPL	N/A	3.0	11.461	34.38
0001-0019583	1	P	070903	011-000-000	HTF	OIL,HYD. FOR TROLLEY 5 C	RPL	N/A	1.0	37.610	37.61
0001-0019583	1	note			REPLACE HYDRAULIC PUMP				**		
0001-0019637	1	L	071003	015-000-000	N/A	EXTERIOR BODY	CHK	0017	1.5	35.000	52.50
0001-0019637	1	note			Operator reports: Bike rack does not lock in the down				**		

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 9
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTEB41WH524120 Odom > 244316.0 Shop: All
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0019637	1	note			position.		**		
0001-0019637	1	note			STRAIGHTENED BENT BIKE RACK		**		
0001-0019660	1	L 071403 026-250-000	N/A		ROAD CALL	RC 0009	1.0	35.000	35.000
0001-0019660	1	note			ROAD CALL TO FERNDALE		**		
0001-0019660	2	L 071403 010-150-000	N/A		FLASHERS FUSES,CIRCU	RPR 0006	0.5	35.000	17.500
0001-0019660	2	P 071403 010-150-000	44690		FLASHER,12V 16 LAMP 33 A	RPR N/A	1.0	15.820	15.820
0001-0019660	2	note			BOTH TURN SIGNALS AND THE 4-WAY FLASHERS WORK INTERMITTENTLY		**		
0001-0019660	2	note			BRAKE LOCK WARNING LIGHT IN THE DASH IS OUT		**		
0001-0019660	2	note			FLASHER REPLACED - DASH LIGHT BULB REPLACED		**		
0001-0019800	1	L 072903 022-200-000	N/A		MECHANICAL	CHK 0011	1.0	35.000	35.000
0001-0019800	1	note			Operator reports: Lift end does not come up, wheel chair		**		
0001-0019800	1	note			could roll off when lifting.		**		
0001-0019800	1	note			DIAGNOSE LIFT PROBLEM, FOUND MICRO SWITCH FOR OUTER BARRIER		**		
0001-0019800	1	note			HAD COME LOOSE AND WAS OUT OF ADJUSTMENT - ADJUSTED SWITCH		**		
0001-0019800	1	note			AND TESTED LIFT OPERATION		**		
0001-0019800	2	L 072903 010-600-000	N/A		P.A. SYSTEM, LABEL M	CHK 0011	0.2	35.000	7.000
0001-0019800	2	note			Operator reports: Speaker is very poor.		**		
0001-0019800	2	note			NO PROBLEM FOUND		**		
0001-0019932	2	L 080403 012-000-000	N/A		AIR SYSTEM	CHK 0006	0.3	35.000	10.500
0001-0019932	2	note			AIR LEAK		**		
0001-0019932	2	note			REPAIRED AIR HOSE AT SEAT CONTROL VALVES		**		
0001-0019932	1	L 080703 024-000-000	N/A		TIRES, TUBES, LINERS	RPR 0017	0.5	35.000	17.500
0001-0019932	1	note			RS O/S dual is flat.		**		
0001-0019932	1	note			INSTALLED SPARE		**		
0001-0019964	1	L 081203 010-350-000	N/A		LIGHTS/CLEARANCE,SKI	CHK 0011	0.5	35.000	17.500
0001-0019964	1	P 081303 010-350-000	7792		SWITCH,FLOOR T/S	CHK N/A	1.0	19.358	19.358
0001-0019964	1	note			Operator reports: Turn signals are sticking on, the lights		**		
0001-0019964	1	note			do not blink but the clicker still clicks.		**		
0001-0019964	1	note			REPLACED LEFT TURN SIGNAL SWITCH		**		
0001-0019968	1	L 081403 004-000-000	N/A		STEERING SYSTEM	RPL 0013	1.0	35.000	35.000
0001-0019968	1	L 081403 004-000-000	N/A		STEERING SYSTEM	RPL 0015	1.0	35.000	35.000
0001-0019968	1	L 081803 004-000-000	N/A		STEERING SYSTEM	RPL 0012	3.0	35.000	105.000
0001-0019968	1	L 081803 004-000-000	N/A		STEERING SYSTEM	RPL 0013	0.3	35.000	10.500
0001-0019968	1	P 081803 004-000-000	26221		LOCTITE,THREADLOCKER #2	RPL N/A	1.0	15.370	15.370
0001-0019968	1	P 081803 004-000-000	8018210		BRACKET,STEER GEAR TO FR	RPL N/A	1.0	201.980	201.980
0001-0019968	1	note			Replace steering gear box bracket		**		

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
NO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROW PAGE: 10
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: AEL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0020038	1	L 082003	022-000-000	N/A	WHEELCHAIR LIFTS	CHK 0013	4.0	35.000	140.00
0001-0020038	1	P 082103	022-000-000	264103	SWITCH,LIMITING (RICON)	CHK N/A	1.0	46.974	46.97
0001-0020038	1	note			Driver reports--tried three times before ramp would stow.		**		
0001-0020038	1	note			ADJUSTED ROLL STOP ARM BENT		**		
0001-0020038	1	note			REPLACED BAD RSTP SWITCH AND WIRES		**		
0001-0020038	1	note			REPAIRED BENT ACTIVATOR CAM		**		
0001-0020038	2	L 082503	008-000-000	N/A	COOLING SYSTEM	CHK 0006	0.5	35.000	17.50
0001-0020038	2	P 082503	008-000-000	ANTIFREEZE	COOLANT,EXTEND SERV. 55G	CHK N/A	8.0	1.021	8.16
0001-0020038	2	note			STARTED UP - RAN FOR ABOUT 30 SECOND AND QUIT		**		
0001-0020038	2	note			DID THIS TWICE.		**		
0001-0020038	2	note			LOW COOLANT - ADDED 2 GALS		**		
0001-0020116	1	L 082703	010-600-000	N/A	P.A. SYSTEM, LABEL M	CHK 0011	0.3	35.000	10.50
0001-0020116	1	note			Operator reports: The P.A. has a very loud high pitch whine		**		
0001-0020116	1	note			that gets higher or lower wht engine speed.		**		
0001-0020116	1	note			COULD NOT DUPLICATE THIS PROBLEM		**		
0001-0020138	1	L 082803	026-250-000	N/A	ROAD CALL	CHK 0015	2.5	35.000	52.50
0001-0020138	1	L 082803	026-250-000	N/A	ROAD CALL	CHK 0008	2.5	35.000	87.50
0001-0020138	1	note			Road call to Ferndale park and ride center.		**		
0001-0020138	3	L 082803	026-400-000	N/A	TOWING	CHK 0011	0.5	35.000	17.50
0001-0020138	3	note			Had coach towed form Ferndale park and ride center back to		**		
0001-0020138	3	note			the shop.		**		
0001-0020136	1	P 082903	025-200-000	LF3000	FILTER,OIL CUMMINS	PM N/A	1.0	18.251	18.25
0001-0020136	1	P 082903	025-200-000	FS1000	FILTER,FUEL USE FOR ORIO	PM N/A	1.0	8.190	8.19
0001-0020136	1	P 082903	025-200-000	4025270	SEAL,FRT. COVER C8.3	PM N/A	1.0	11.260	11.26
0001-0020138	2	L 082903	012-000-000	N/A	AIR SYSTEM	CHK 0013	8.0	35.000	280.00
0001-0020138	2	P 082903	012-000-000	3913287	GASKET,HYD PUMP C8.3L TR	CHK N/A	1.0	7.410	7.41
0001-0020138	2	P 082903	012-000-000	3558051RX	COMPRESSOR,UX 15CFM TROL	CHK N/A	1.0	658.500	658.50
0001-0020138	2	P 082903	012-000-000	3918340	GASKET,AIR COMP MIN TROL	CHK N/A	1.0	0.680	0.68
0001-0020138	2	P 082903	012-000-000	3917780	GASKET,COVER FRT. TROLLE	CHK N/A	1.0	17.620	17.62
0001-0020138	2	P 082903	012-000-000	3823494	SEALANT,GREY SILICONE	CHK N/A	1.0	8.500	8.50
0001-0020138	2	note			Operator reports: Loud noise from engine compartment.		**		
0001-0020138	2	note			REPLACED COMPRESSOR, HOOK UP DIRVE LINE		**		
0001-0020138	2	note			INSTALLED COVER PLATE		**		
0001-0020136	1	L 083003	025-200-000	N/A	PM B (6,000 & 12,000	PM 0013	1.0	35.000	35.00
0001-0020136	2	L 083003	008-300-000	N/A	WATER PUMP ASSEMBLY	RPL 0013	1.0	35.000	35.00
0001-0020136	2	P 083003	008-300-000	S1003A	SLEEVE,RUBBER COMPR. WAT	RPL N/A	4.0	0.632	2.52

DATE: 02/16/2006
 Time: 12:18 p.m.

WIGATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 11
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LDMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QUY	PRICE/WG	TOTAL COST
0001-0020136	2	P 083003	008-300-000	154916	GASKET,PUMP	RPL N/A	1.0	1.796	1.79
0001-0020136	2	note			THERMOSTATE HOUSING LEAK		**		
0001-0020136	2	note			REMOVED UP HOSE ON THERMOSTATE HOUSING		**		
0001-0020136	2	note			INSTALLED NEW CLAMPS - SEALED HOSE		**		
0001-0020138	2	L 083003	012-000-000	N/A	AIR SYSTEM	CHK 0013	6.0	35.000	210.00
0001-0020138	2	note			Operator reports: Loud noise from engine compartment.		**		
0001-0020138	2	note			REPLACED COMPRESSOR, HOOK UP DIRVE LINE		**		
0001-0020138	2	note			INSTALLED COVER PLATE		**		
0001-0020157	1	P 090203	025-200-000	3913287	GASKET,HYD POMP C8.3L TR	PM N/A	1.0-	7.410	7.41
0001-0020157	1	P 090203	025-200-000	WF2121	FILTER,EXTEND SERV TIME	PM N/A	1.0	37.280	37.28
0001-0020157	1	P 090203	025-200-000	WF2121	FILTER,EXTEND SERV TIME	PM N/A	1.0-	37.280	37.28
0001-0020157	2	P 090203	008-050-000	WF2121	FILTER,EXTEND SERV TIME	RPL N/A	1.0	37.280	37.28
0001-0020157	1	L 090303	025-200-000	N/A	PM B (6,000 & 12,000	PM 0013	6.0	35.000	280.00
0001-0020157	1	L 090303	025-200-000	N/A	PM B (6,000 & 12,000	PM 0017	3.5	35.000	122.50
0001-0020157	3	L 090303	010-300-000	N/A	INDICATOR:GAUGE,METE	CHK 0017	1.0	35.000	35.00
0001-0020157	3	P 090303	010-300-000	R8760	GUAGE,VOLTMETER CHR BEZE	CHK N/A	1.0	22.040	22.04
0001-0020157	3	note			REAR GAGUE FRONT GAUGE HEAD 16.5 - 14.0 VOLTS		**		
0001-0020157	4	L 090303	024-410-000	N/A	TIRE REPLACE/REAR/RE	RPL 0013	0.5	35.000	17.50
0001-0020157	4	P 090303	024-410-000	TIRE	TIRE	RPL N/A	4.0	169.040	676.16
0001-0020157	4	note			NEEDS REAR TIRES		**		
0001-0020222	2	OP 090903	015-200-000	LFS	CUPOLA WORE	OUT N/A	1.0	43.830	43.83
0001-0020222	1	note			REPAIR DONE IN JUNE.		**		
0001-0020222	1	note			LFS INVOICE		**		
0001-0020222	2	OP 090903	026-400-000	BERK'S	TOWING	OUT N/A	1.0	305.670	305.67
0001-0020222	2	note			TOWED IN FROM AXTON ROAD ON 8/28		**		
0001-0020269	1	L 091003	026-250-000	N/A	ROAD CALL	RC 0006	1.0	35.000	35.00
0001-0020269	1	L 091003	026-250-000	N/A	ROAD CALL	RC 0013	1.5	35.000	52.50
0001-0020269	1	note			Engine quit in driveway of Lynden Food Pavilion parking		**		
0001-0020269	1	note			lot.		**		
0001-0020269	1	note			COACH WAS OUT OF FUEL - ADDED FUEL, PRIMED FILTER - RETURNED		**		
0001-0020269	1	note			TO BASE		**		
0001-0020269	4	L 091503	013-000-000	N/A	HEATING/AIR CONDITIO	CHK 0014	2.0	35.000	70.00
0001-0020269	4	note			NO DRFROST OR FRONT END HEAT AT ALL		**		
0001-0020269	4	note			REAR HEAT BARELY WARM		**		
0001-0020307	1	L 091603	015-100-000	N/A	EXTERIOR MIRRORS	CHK 0013	1.0	35.000	35.00
0001-0020307	1	note			Right side mirror motor bad		**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROW PAGE: 12
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LcMiles > 244316.0

WO#	LN	TRN TYP DATE	VMS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0020307	1	note		ORDERED MOTOR			**		
0001-0020307	2	L 091603	015-200-000	N/A	BODY REPAIR/INCIDENT	RPR 0013	1.0	35.000	35.00
0001-0020307	2	note		RAIN WATER IN BUS			**		
0001-0020269	2	L 091703	020-200-000	N/A	OTHER SEATS	CHK 0014	0.7	35.000	24.50
0001-0020269	2	note		SEAT ON CURBSIDE SEAT DIRECTLY BEHIND THE REAR DOOR THE			**		
0001-0020269	2	note		FORWARD BOLT IS BACKING OUT			**		
0001-0020269	2	note		THE 3RD DOWN BELL CORD FROM THE BACK IS BROKEN			**		
0001-0020269	3	L 091703	010-600-000	N/A	P.A. SYSTEM, LAPEL M	CHK 0014	0.3	35.000	10.50
0001-0020269	3	note		PA HAS A LOUD WHINE THAT DROWNS OUT MY VOICE			**		
0001-0020307	3	L 091803	008-000-000	N/A	COOLING SYSTEM	RPR 0014	0.5	35.000	17.50
0001-0020307	3	note		COOLANT LEVEL WARNING LIGHT HAS COME ON SEVERAL TIMES			**		
0001-0020307	3	note		REPLACED THERMOSTAT SEAL AND 3 GASKETS			**		
0001-0020307	1	L 092303	015-100-000	N/A	EXTERIOR MIRRORS	CHK 0017	1.0	35.000	35.00
0001-0020307	1	P 092303	015-100-000	3913028	THERMOSTAT, CB. JL 1 PER E	CHK N/A	1.0	20.757	20.75
0001-0020307	1	P 092303	015-100-000	3913027	GASKET, T'STAT HOUSING	CHK N/A	1.0	4.800	4.80
0001-0020307	1	P 092303	015-100-000	3913025	GASKET, STAT HSG 0.3	CHK N/A	1.0	2.960	2.96
0001-0020307	1	P 092303	015-100-000	188318	SEAL, THERMOSTAT CB. 3L	CHK N/A	1.0	7.625	7.62
0001-0020307	1	P 092303	015-100-000	3913032	GASKET, OUTLET STAT HSG.	CHK N/A	1.0	3.500	3.50
0001-0020307	1	P 092303	015-100-000	10329	CAP, RADIATOR W/LEVER TRO	CHK N/A	1.0	4.990	4.99
0001-0020307	1	P 092303	015-100-000	CT300L	CLAMP, CONSTANT TORQUE	CHK N/A	1.0	4.270	4.27
0001-0020307	1	P 092303	015-100-000	CT175L	CLAMP, CONSTANT TORQUE	CHK N/A	1.0	4.100	4.10
0001-0020307	1	P 092303	015-100-000	GL1905032-900	MIRROR, FLAT, HEATED 12V	CHK N/A	1.0	20.230	20.23
0001-0020307	1	P 092303	015-100-000	GL1905032-900	MIRROR, FLAT, HEATED 12V	CHK N/A	1.0	20.230	20.23
0001-0020307	1	P 092303	015-100-000	S20A1233	MIRROR GLASS, HEAT CONVEX	CHK N/A	1.0	20.130	20.13
0001-0020307	2	note		Right side mirror motor bad			**		
0001-0020307	1	note		ORDERED MOTOR			**		
0001-0020307	3	L 092303	008-000-000	N/A	COOLING SYSTEM	RPR 0017	7.5	35.000	262.50
0001-0020307	3	note		COOLANT LEVEL WARNING LIGHT HAS COME ON SEVERAL TIMES			**		
0001-0020307	3	note		REPLACED THERMOSTAT SEAL AND 3 GASKETS			**		
0001-0020356	1	T 092303	007-000-000	N/A	ENGINE SYSTEM	CHK 0017	0.5	35.000	17.50
0001-0020356	1	P 092303	007-000-000	SAMPLE TUBING	TUBING, OIL SAMPLE 1/4 SE	CHK N/A	3.0	0.129	0.38
0001-0020356	1	P 092303	007-000-000	SAMPLE TUBING	TUBING, OIL SAMPLE 1/4 SE	CHK N/A	4.0	0.129	0.51
0001-0020356	1	note		TAKE OIL SAMPLE			**		
0001-0020386	1	L 092403	007-000-000	N/A	ENGINE SYSTEM	RC 0006	1.0	35.000	35.00
0001-0020386	1	L 092403	007-000-000	N/A	ENGINE SYSTEM	RC 0013	1.0	35.000	35.00
0001-0020386	2	L 092403	007-000-000	N/A	ENGINE SYSTEM	RC 0015	0.5	35.000	17.50

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 13
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LIMiles > 244316.0

WO#	LN	TYP	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0020386	1	note				Road call to Pole and Guide- Fuel leaking from engine area			**		
0001-0020386	1	note				BUS SWAP			**		
0001-0020386	1	note				REPLACED FUEL LINE - WASH ENGINE COMPARTMENT			**		
0001-0020386	2	L	092403	013-000-000	N/A	HEATING/ALA CONDITIO	RPR	0015	0.5	35.000	17.500
0001-0020386	2	note				NO UP FRONT HEAT OR DEFROST			**		
0001-0020386	2	note				POPPED BREAKER			**		
0001-0020429	4	L	100103	010-360-000	N/A	LIGHTS-INTERIOR	RPR	0015	0.3	35.000	10.500
0001-0020429	4	L	100203	010-360-000	N/A	LIGHTS-INTERIOR	RPR	0014	0.5	35.000	17.500
0001-0020429	4	note				DRIVER'S LITE WENT OUT			**		
0001-0020429	4	note				REPLACED BULB			**		
0001-0020429	3	L	100603	010-350-000	N/A	LIGHTS/CLEARANCE, SK1	RPR	0006	0.3	35.000	10.500
0001-0020429	3	note				R FRONT PARKING LIGHT OUT			**		
0001-0020429	3	note				REPLACED BULB IN LIGHT			**		
0001-0020429	2	L	100903	018-000-000	N/A	DOORS & REMOVABLE PA	RPR	0015	1.0	35.000	35.000
0001-0020429	2	note				FRONT DOOR IS SO SLOW			**		
0001-0020429	2	note				ADJUSTE DOOR SPEED AT MOTOR			**		
0001-0020507	1	L	101003	025-500-000	N/A	PM E - ORION (48,000	PM	0009	8.0	35.000	280.000
0001-0020507	1	L	101003	025-500-000	N/A	PM E - ORION (48,000	PM	0014	7.5	35.000	262.500
0001-0020507	1	P	101003	025-500-000	PME98CC	KIT-CABLE CAR E-1998	PM	N/A	1.0	0.000	0.000
0001-0020507	1	P	101003	025-500-000	FS1000	FILTER, FUEL USE FOR ORIO	PM	N/A	1.0	8.242	8.242
0001-0020507	1	P	101003	025-500-000	FS1251	FILTER, FUEL TROLLEY	PM	N/A	1.0	6.614	6.614
0001-0020507	1	P	101003	025-500-000	LF3000	FILTER, OIL CUMMINS	PM	N/A	1.0	18.376	18.376
0001-0020507	1	P	101003	025-500-000	CC2610	CLEANER, RAD FLOSH "RESTO	PM	N/A	1.0	13.060	13.060
0001-0020507	1	P	101003	025-500-000	BF932	FILTER, WEBASTO	PM	N/A	1.0	1.880	1.880
0001-0020507	1	P	101003	025-500-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM	N/A	2.0	7.500	15.000
0001-0020507	1	P	101003	025-500-000	29540493	FILTER, TRANS ALLISON	PM	N/A	1.0	65.599	65.599
0001-0020507	1	P	101003	025-500-000	C8016552	FILTER, HYDRAULIC, STEERIN	PM	N/A	3.0	10.856	32.568
0001-0020507	1	P	101003	025-500-000	107794X	CARTRIDGE, AIR DRYER AD9	PM	N/A	1.0	31.200	31.200
0001-0020507	1	P	101003	025-500-000	3920773	WASHER, SEALING TROLLEY O	PM	N/A	2.0	0.753	0.753
0001-0020507	1	P	101003	025-500-000	5C438	FILTER, HEATER TROLLEY	PM	N/A	1.0	5.130	5.130
0001-0020507	1	P	101003	025-500-000	PME98CC	END-CABLE CAR E-1998	PM	N/A	1.0	0.000	0.000
0001-0020507	1	P	101003	025-500-000	CC2610	CLEANER, RAD FLOSH "RESTO	PM	N/A	1.0	13.060	13.060
0001-0020507	1	P	101003	025-500-000	BF932	FILTER, WEBASTO	PM	N/A	1.0	1.880	1.880
0001-0020507	1	P	101003	025-500-000	15W-40L	OIL, LUBE/OCM TANK ONLY!!	PM	N/A	25.0	0.790	19.750
0001-0020507	1	P	101003	025-500-000	ATF	OIL, AUTOMATIC TRANSMISSI	PM	N/A	17.0	0.892	15.164
0001-0020507	1	P	101003	025-500-000	80W-90	OIL, GEAR LUBE 410# DRUM	PM	N/A	15.5	0.971	15.051

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

TO: 3-412/ROV PAGE: 14
 Vch: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LrMiles > 244316.0

WOI	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTZ	PRICE/WG	TOTAL COST
0001-0020507	2	P	101003	008-050-000	CC2607C	STRIP,TEST COOLANT 25/BO	PM	N/A	1.0	1.700	1.70
0001-0020507	2	note			ES COMPLETE				**		
0001-0020507	3	L	101003	013-000-000	N/A	HEATING/AIR CONDITIO	RPR	0013	2.0	35.000	70.00
0001-0020507	3	note			INSIDE HEATER BROKEN LOGSE ON GROUND FLOOR				**		
0001-0020507	3	note			REMOVE PART OF SEAT TO REPAIR				**		
0001-0020507	4	L	101003	010-000-000	N/A	ELECTRICAL/INSTRMNT	RPR	0004	1.5	35.000	52.50
0001-0020507	4	note			MISC LIGHTS				**		
0001-0020507	5	L	101003	011-000-000	N/A	HYDRAULIC SYSTEM	RPR	0009	3.0	35.000	105.00
0001-0020507	5	L	101003	011-000-000	N/A	HYDRAULIC SYSTEM	RPR	0009	1.0	35.000	35.00
0001-0020507	5	note			REPAIR HYD LEAKS				**		
0001-0020507	5	note			OTHER REPAIRS				**		
0001-0020507	1	L	101103	025-500-000	N/A	PM E - ORION (48,000	PM	0009	1.5	35.000	52.50
0001-0020507	1	L	102103	025-500-000	N/A	PM E - ORION (48,000	PM	0017	7.0	35.000	245.00
0001-0020429	1	L	101303	009-200-000	N/A	FUEL LINES,T\FITTING	OTH	0004	2.0	35.000	70.00
0001-0020429	1	P	101303	009-200-000	801-4	HOSE,PUSHLOK 1/4"	OTH	N/A	3.0	0.900	2.70
0001-0020429	1	P	101303	009-200-000	34982-14-4	UNION,BANJO 14-4	OTH	N/A	1.0	6.600	6.60
0001-0020429	1	P	101303	009-200-000	34982-12-4	UNION,BANJO 12-4	OTH	N/A	1.0	4.232	4.23
0001-0020429	1	note			Upgrade rubber fuel hose to steel braided hose				**		
0001-0020507	1	L	101303	025-500-000	N/A	PM E - ORION (48,000	PM	0004	4.0	35.000	140.00
0001-0020507	1	P	101303	025-500-000	109578	KIT,HEATER AD9 12V TROLL	PM	N/A	1.0	22.660	22.66
0001-0020507	1	P	101303	025-500-000	5005037	KIT,AIR DRYER AD9 MAINT.	PM	N/A	1.0	21.961	21.96
0001-0020507	1	P	101303	025-500-000	HTF	OIL,HYD. FOR TROLLEY 5 G	PM	N/A	1.0	37.415	37.41
0001-0020507	1	P	101303	025-500-000	1911577	BELT,SERP. TROLLEY OLD #	PM	N/A	1.0	13.840	13.84
0001-0020507	1	P	101303	025-500-000	BF932	FILTER,WEBASTO	PM	N/A	1.0	1.880	1.88
0001-0020507	1	P	101303	025-500-000	886-41A	NOZZLE,0.35 60 DEGREE	PM	N/A	1.0	10.099	10.09
0001-0020507	1	P	101303	025-500-000	89	LAMP	PM	N/A	1.0	0.310	0.31
0001-0020507	1	P	101303	025-500-000	815-5522	SUPPORT,DOOR	PM	N/A	1.0	21.110	21.11
0001-0020507	7	L	101303	013-100-000	N/A	WEBASTO HEATER	RPR	0011	2.0	35.000	70.00
0001-0020507	7	note			REPLACED NOZZLE FOR WEBASTO				**		
0001-0020507	7	note			TEST OPERATION				**		
0001-0020429	1	L	101403	009-200-000	N/A	FUEL LINES,T\FITTING	OTH	0009	1.0	35.000	35.00
0001-0020429	1	note			Upgrade rubber fuel hose to steel braided hose				**		
0001-0020507	1	P	101403	025-500-000	1677045C1	GASKET,HYD TANK TROLLEY	PM	N/A	1.0	1.210	1.21
0001-0020507	1	P	101403	025-500-000	CFW500	CHANNEL,SLIDER DRIVERS T	PM	N/A	1.0	2.000	2.00
0001-0020507	1	P	101403	025-500-000	KIT6115ACL	SHOE,KIT TROLLEY REAR W/	PM	N/A	2.0	179.058	358.11
0001-0020507	1	P	101403	025-500-000	66884R	DRUM,REAR TROLLEY REBUIL	PM	N/A	1.0	182.740	182.74

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

10: 3-412/ROW PAGE: 15
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LFKiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0020507	1	P 101403	025-500-000	370023A	SEAL, REAR AXLE TROLLEY	EM N/A	2.0	27.903	55.80
0001-0020507	1	P 101403	025-500-000	13-7110	GASKET, AXLE, REAR (CABLE	EM N/A	2.0	0.910	1.82
0001-0020507	6	L 101403	005-200-000	N/A	RELINE, REAR	RPL 0009	3.0	35.000	105.00
0001-0020507	6	note		REAR BRAKE JOB			**		
0001-0020507	1	P 101503	025-500-000	13-7208	WEDGE, HUB TROLLEY	PM N/A	24.0	0.849	20.37
0001-0020507	6	L 101503	005-200-000	N/A	RELINE, REAR	RPL 0009	5.0	35.000	175.00
0001-0020507	6	L 101503	005-200-000	N/A	RELINE, REAR	RPL 0009	3.0	35.000	105.00
0001-0020507	6	note		REAR BRAKE JOB			**		
0001-0020507	1	P 101603	025-500-000	3926380	FITTING, BANJO FUEL	PM N/A	1.0	14.290	14.29
0001-0020507	1	P 101603	025-500-000	3916361	FITTING, BANJO SMALL FUEL	PM N/A	1.0	2.290	2.29
0001-0020507	1	P 101603	025-500-000	3918188	WASHER	PM N/A	2.0	0.740	1.48
0001-0020507	1	P 101603	025-500-000	3963983	WASHER	PM N/A	2.0	0.390	0.78
0001-0020507	2	P 101603	008-050-000	ANTIFREEZEB	COOLANT, EXTEND SERV. 55G	PM N/A	2.0	1.021	2.04
0001-0020507	2	note		ES COMPLETE			**		
0001-0020598	1	L 101803	001-000-000	N/A	FRONT AXLE	CHK 0017	6.0	35.000	210.00
0001-0020598	1	note		Inspect front wheel bearing. Replace if any evidence of heat			**		
0001-0020598	1	note		or other damage. Adjust according to the service manual.			**		
0001-0020598	1	note		REPLACED FRONT WHEEL BEARINGS AND SEALS AND ADJUSTED			**		
0001-0020598	2	L 101803	005-000-000	N/A	BRAKE SYSTEM	RPR 0017	1.0	35.000	35.00
0001-0020598	2	note		HOT BRAKE SMELL FROM FRONT			**		
0001-0020598	2	note		INSPECTED AND ADJUSTED BRAKES TEST DRIVE OK			**		
0001-0020598	1	P 102003	002-000-000	2208N430	GASKET, FRONT AXLE CAP-TR	CHK N/A	2.0	0.950	1.90
0001-0020598	1	P 102003	001-000-000	370001A	SEAL, OIL (TROLLEY FRONT	CHK N/A	2.0	21.732	43.46
0001-0020598	1	P 102003	001-000-000	HM212011	CUP, BEARING INNER	CHK N/A	2.0	8.733	17.46
0001-0020598	1	P 102003	001-000-000	HM212049	BEARING, CONE INNER	CHK N/A	2.0	13.797	27.59
0001-0020598	1	P 102003	001-000-000	3720	CUP, BEARING OUTER	CHK N/A	2.0	4.630	9.26
0001-0020598	1	P 102003	001-000-000	3782	BEARING, OUTER	CHK N/A	2.0	10.035	20.07
0001-0020598	1	note		Inspect front wheel bearing. Replace if any evidence of heat			**		
0001-0020598	1	note		or other damage. Adjust according to the service manual.			**		
0001-0020598	1	note		REPLACED FRONT WHEEL BEARINGS AND SEALS AND ADJUSTED			**		
0001-0020639	1	L 102103	010-000-000	N/A	ELECTRICAL/INSTRMNT SYST	RPR 0015	0.5	35.000	17.50
0001-0020639	1	P 102303	010-000-000	5582	SWITCH, TOGGLE ON/OFF 2 S	RPR N/A	1.0	3.471	3.47
0001-0020639	1	note		Dest. sign light switch beats up when in on position			**		
0001-0020679	1	L 102303	010-350-000	N/A	LIGHTS/CLEARANCE, SKIRT, S	RPR 0006	1.0	35.000	35.00
0001-0020679	1	note		LH rear side clearance light is out			**		
0001-0020679	1	note		REPLACE LIGHT ASSY			**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

TO: 3-412/POV PAGE: 16
 Veh: 0001-008

Year > 1997 Make > TROLLEY Ser. Num. > LC9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47G30C Miles > 244316.0

WO#	LN	TRN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0020679	2	L	102303	013-200-000	N/A	HEATER FANS	RPL 0006			0.5	35.000	17.500
0001-0020679	2	note				Dash fan is loose , won't stay in position				**		
0001-0020679	2	note				REPLACED FAN				**		
0001-0020679	1	P	102703	010-350-000	1113A	LAMP, SIDE INDICATOR TROL	RPR N/A			1.0	9.980	9.980
0001-0020679	1	P	102703	010-350-000	7-941	LAMP, DEFROSTER 12V	RPR N/A			1.0	54.810	54.810
0001-0020679	1	note				LH rear side clearance light is out				**		
0001-0020679	1	note				REPLACE LIGHT ASSY				**		
0001-0020656	1	P	102803	007-020-000	05088	CLEANER, BRAKE	CHK N/A			1.0	1.370	1.370
0001-0020656	1	L	102803	007-020-000	N/A	TUNE-UP	CHK 0009			6.0	35.000	210.000
0001-0020656	1	note				TUNE UP				**		
0001-0020706	2	P	102903	008-000-000	69842	FITT, BRASS PIPE CAP 3/8	CHK N/A			1.0	0.770	0.770
0001-0020706	2	P	102903	008-000-000	69935	FITT, HOSEBARB 5/8X3/8	CHK N/A			1.0	0.730	0.730
0001-0020706	2	P	102903	008-000-000	92208	CLAMP, HOSE SILICONE 1/2	CHK N/A			2.0	1.061	2.122
0001-0020706	2	P	102903	008-000-000	802416L	HOSE, HEATER, 5/8	CHK N/A			5.0	5.110	25.550
0001-0020706	2	note				COOLANT LEAK				**		
0001-0020706	2	note				REPLACE HEATER HOSE @ RIGHT REAR HEATER				**		
0001-0020706	1	L	102903	026-250-000	N/A	ROAD CALL	RC 0009			2.0	35.000	70.000
0001-0020706	1	note				ROAD CALL TO LYNDEN TERMINAL				**		
0001-0020706	1	note				COOLANT LEAK				**		
0001-0020706	2	L	102903	008-000-000	N/A	COOLING SYSTEM	CHK 0012			1.5	35.000	52.500
0001-0020706	2	note				COOLANT LEAK				**		
0001-0020706	2	note				REPLACE HEATER HOSE @ RIGHT REAR HEATER				**		
0001-0020748	1	P	103103	013-200-000	BREAKER30	CIRCUIT BREAKER, 30A TROL	RPR N/A			1.0	5.433	5.433
0001-0020748	1	L	103103	013-200-000	N/A	HEATER FANS	RPR 0013			0.5	35.000	17.500
0001-0020748	1	note				I had to reset circuit breaker for defrost several times				**		
0001-0020748	1	note				today.				**		
0001-0020748	1	note				REPLACED BREAKER - RUN DEFROST				**		
0001-0020716	1	L	110303	019-000-000	N/A	WINDOWS/GLASS	RPR 0004			2.0	35.000	70.000
0001-0020716	1	note				The rear emergency exit window latch is broken				**		
0001-0020716	1	note				INSTALLED NEW PART				**		
0001-0020857	2	L	110503	010-150-000	N/A	FLASHERS FUSERS, CIRCUIT	RPR 0017			0.5	35.000	17.500
0001-0020857	2	note				FLASHER FRONT LOWER MECH BROKEN WIRE NEED TO REPLACE WHOLE				**		
0001-0020857	2	note				UNIT				**		
0001-0020857	2	note				RESOLDERED GROUND WIRE				**		
0001-0020857	1	L	110603	007-000-000	N/A	ENGINE SYSTEM	RPR 0011			1.5	35.000	52.500
0001-0020857	1	L	110603	007-000-000	N/A	ENGINE SYSTEM	RPR 0016			1.5	35.000	52.500

DATE: 02/16/2006
 Time: 12:10 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROV PAGE: 17
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > IC9VTE841W1524120 Odom > 244316.0 Shop: All
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0020857	1	L 110603	007-000-000	N/A	ENGINE SYSTEM	RPR 0015	0.5	35.000	17.50
0001-0020857	1	note			Road call to FTC. Engine oil leak. Hydraulic pump mounts		**		
0001-0020857	1	note			loose.		**		
0001-0020857	1	note			SWAPPED COACH- PUT NUT ON AIR COMPRESSOR STOD AND TIGHTENED		**		
0001-0020857	1	note			BOTH NUTS, CHECKED FOR LEAKS		**		
0001-0020857	1	note			CLEAN ENGINE AND BACK OF BUS		**		
0001-0020716	2	L 111003	015-200-000	N/A	BODY REPAIR/INCIDENTAL	RPR 0006	0.5	35.000	17.50
0001-0020716	2	note			LEAK RUNNING DOWN TROLLEY BELL HANDLE - WET FLOOR		**		
0001-0020716	2	note			SEALED AROUND TOP END OF PULL CORD		**		
0001-0021029	1	P 112403	010-200-000	PM322	MOTOR, BLOWER - TROLLEY	RPR N/A	1.0	64.690	64.69
0001-0021029	1	L 112403	010-200-000	N/A	DEVICE: WIRING/HARNESS	RPR 0016	1.0	35.000	35.00
0001-0021029	1	note			Defroster fans trip circuit breakers.		**		
0001-0021029	1	note			REPLACED RIGHT REAR HEATER FAN MOTOR		**		
0001-0021029	1	note			CHECK TURBO FOR AIR LEAKS AND LOOSE BEARINGS		**		
0001-0020716	2	P 112603	015-200-000	GFW049	HANDLE, SAFETY RED W/ALUM	RPR N/A	1.0	47.500	47.50
0001-0020716	2	P 112603	015-200-000	GFW900	KIT, RECEIVER FOR RED SAF	RPR N/A	1.0	17.350	17.35
0001-0020716	2	note			LEAK RUNNING DOWN TROLLEY BELL HANDLE - WET FLOOR		**		
0001-0020716	2	note			SEALED AROUND TOP END OF PULL CORD		**		
0001-0021033	1	P 112603	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM N/A	1.0	8.254	8.25
0001-0021033	1	P 112603	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM N/A	1.0	6.745	6.74
0001-0021033	1	P 112603	025-200-000	LP3000	FILTER, OIL CUMMINS	PM N/A	1.0	18.396	18.39
0001-0021033	1	P 112603	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM N/A	1.0	7.500	7.50
0001-0021033	1	P 112603	025-200-000	LN6 NUT	NUT, 1" GR.8NF NYLOK RADI	PM N/A	1.0	1.616	1.61
0001-0021033	1	P 112603	025-200-000	1X6NF	BOLT, RADIUS ROD BUSHING	PM N/A	1.0	5.400	5.40
0001-0021033	1	P 112603	025-200-000	15W-40L	OIL, LUBEROOM TANK ONLY!!	PM N/A	37.0	0.785	29.04
0001-0021033	1	L 112603	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0016	5.0	35.000	175.00
0001-0021033	1	L 112603	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0013	4.0	35.000	140.00
0001-0021033	3	L 112603	003-000-000	N/A	SUSPENSION SYSTEM	RPR 0013	0.7	35.000	24.50
0001-0021033	3	note			RADIUS ROD BOLT BROKEN		**		
0001-0021033	3	note			REMOVED AND REPLACED NUT AND BOLT		**		
0001-0021033	4	L 112603	012-000-000	N/A	AIR SYSTEM	RPR 0013	0.6	35.000	21.00
0001-0021033	4	note			AIR LINES LEAKING AT 4-14 VALVE		**		
0001-0021033	4	note			REMOVE AIR LINES - RESEALED		**		
0001-0021033	5	L 112603	016-000-000	N/A	INTERIOR PANELS & SPECIA	RPR 0013	1.6	35.000	56.00
0001-0021033	5	note			R/SIDE WINDOW LATCH BAD - REPLACED LOWER PART OF WINDOW WITH		**		
0001-0021033	5	note			LATCH		**		

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/30V
Veh: 0001-808
PAGE: 18

Year > 1997 Make > TROLLEY Ser. Num. > IC9VTE841WH524120 Odom > 244316.0 Shop: AJL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LOMiles > 244316.0

WO#	LN	TRN TYP DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0021033	5	note			STANCHIONS GRAB RAIL BRACKET BROKEN - REPLACED		**		
0001-0021033	6	I 112603	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	1.0	35.000	35.000
0001-0021033	6	L 112603	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0013	1.5	35.000	52.500
0001-0021033	6	note			LIFT REPAIR		**		
0001-0021033	6	note			REPAIRED ROLLER		**		
0001-0021033	6	note			REPLACED MISSING BOLT ON BEARING SUPPORT, SUPPORT WAS		**		
0001-0021033	6	note			BENDING		**		
0001-0021033	1	P 112803	025-200-000	GFWD49	HANDLE, SAFETY RED W/AJUM	PM N/A	1.0	47.500	47.500
0001-0021033	1	P 112803	025-200-000	5C438	FILTER, HEATER TROLLEY	PM N/A	1.0	5.330	5.330
0001-0021033	1	P 112803	025-200-000	HBR011	BRACKET, HANDRAIL TROLLEY	PM N/A	1.0	16.500	16.500
0001-0021033	1	L 112803	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0011	0.5	35.000	17.500
0001-0021101	1	L 120203	010-350-000	N/A	LIGHTS/CLEARANCE, SKIRT, S	RPR 0006	0.3	35.000	10.500
0001-0021101	1	note			Center brake light doesn't work		**		
0001-0021101	1	note			REPLACED LAMP ASSY		**		
0001-0021101	2	L 120203	010-360-000	N/A	LIGHTS-INTERIOR	RPR 0006	0.5	35.000	17.500
0001-0021101	2	note			Speedometer light is out		**		
0001-0021101	2	note			REPLACED BULB AND SOCKET		**		
0001-0021101	3	L 120203	021-000-000	N/A	FARE BOXES	RPR 0006	0.2	35.000	7.000
0001-0021101	3	note			Escrow light in GFI doesn't work		**		
0001-0021101	3	note			REPLACED BULB		**		
0001-0021101	1	P 120303	010-350-000	52892-3	LAMP, SEALED MODEL 60	RPR N/A	1.0	5.839	5.839
0001-0021101	1	P 120303	010-350-000	25100	SOCKET, LAMP DASH (168/19)	RPR N/A	1.0	1.060	1.060
0001-0021101	1	note			Center brake light doesn't work		**		
0001-0021101	1	note			REPLACED LAMP ASSY		**		
0001-0021136	1	L 120503	015-000-000	N/A	EXTERIOR BODY	RPR 0008	1.0	35.000	35.000
0001-0021136	1	note			Engine compartment door LH latch is missing the latch arm		**		
0001-0021136	1	note			REPLACED LATCH ASSEMBLY - ADJUST DOOR LATCHES		**		
0001-0021142	1	L 120603	005-000-000	N/A	BRAKE SYSTEM	CHK 0008	1.5	35.000	52.500
0001-0021142	1	note			Brakes moaning too much as you go to a stop		**		
0001-0021142	1	note			REAR BRAKES HOWL LAST 20 FEET OF STOP		**		
0001-0021142	1	note			LINING AT 12/32 THICKNESS - DRUMS LOOK GOOD - MAYBE AN OFF		**		
0001-0021142	1	note			BRAND LINING		**		
0001-0021142	1	note			RELINE REAR BRAKES		**		
0001-0021136	1	P 120803	015-000-000	62-40-251-2	LATCH, COMPARTMENT DOOR T	RPR N/A	1.0	26.900	26.900
0001-0021136	1	note			Engine compartment door LH latch is missing the latch arm		**		
0001-0021136	1	note			REPLACED LATCH ASSEMBLY - ADJUST DOOR LATCHES		**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 19
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841W01524120 Odcm > 244316.0 Shop: ALL
 Dept > 30 Model > CARLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WCH	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0021142	1	P 120803	005-000-000	4515QJ1BG	KIT,SPRINC & ROLLER TROL	CHK N/A	1.0	5.650	5.650
0001-0021142	1	note			Brakes moaning too much as you go to a stop		**		
0001-0021142	1	note			REAR BRAKES HOWL LAST 20 FEET OF STOP		**		
0001-0021142	1	note			LINING AT 12/32 THICKNESS - DRUMS LOOK GOOD - MAYBE AN OFF		**		
0001-0021142	1	note			BRAND LINING		**		
0001-0021142	1	note			RELINE REAR BRAKES		**		
0001-0021208	1	L 121103	022-000-000	N/A	WHEELCHAIR LIFTS	SPR 0006	1.0	35.000	35.000
0001-0021208	1	note			WCL will not fully deploy - TIGHTENED GUIDE PIN ON "FOOT"		**		
0001-0021208	1	note			CHECK SWITCH ADJUSTEMENT, ADJUSTED ROO-STOP CLOSE LINKAGE		**		
0001-0021142	1	P 121503	005-000-000	SAMPLE TUBING	TUBING,OIL SAMPLE 1/4 SE	CHK N/A	5.0	0.130	0.650
0001-0021142	1	P 121503	005-000-000	KIT6115ACT	SHOE,KIT TROLLEY REAR W/	CHK N/A	2.0	179.009	358.018
0001-0021142	1	P 121503	005-000-000	KSR6094524Q	KIT,SHOES-FRONT TROLLEY	CHK N/A	2.0	123.355	246.710
0001-0021142	1	P 121503	005-000-000	R930135	DRUM,FRONT TROLLEY-MERIT	CHK N/A	2.0	232.180	464.360
0001-0021142	1	P 121503	005-000-000	05088	CLEANER,BRAKE	CHK N/A	1.0	1.370	1.370
0001-0021142	1	note			Brakes moaning too much as you go to a stop		**		
0001-0021142	1	note			REAR BRAKES HOWL LAST 20 FEET OF STOP		**		
0001-0021142	1	note			LINING AT 12/32 THICKNESS - DRUMS LOOK GOOD - MAYBE AN OFF		**		
0001-0021142	1	note			BRAND LINING		**		
0001-0021142	1	note			RELINE REAR BRAKES		**		
0001-0021142	2	L 121503	005-100-000	N/A	RELINE, FRONT	CHK 0013	6.0	35.000	210.000
0001-0021142	2	note			FRONT RELINE		**		
0001-0021142	1	L 121503	005-000-000	N/A	BRAKE SYSTEM	CHK 0009	7.5	35.000	262.500
0001-0021142	1	P 121503	005-000-000	5902	GUARD,WHEEL TROLLEY	CHK N/A	2.0	3.037	6.074
0001-0021142	1	note			Brakes moaning too much as you go to a stop		**		
0001-0021142	1	note			REAR BRAKES HOWL LAST 20 FEET OF STOP		**		
0001-0021142	1	note			LINING AT 12/32 THICKNESS - DRUMS LOOK GOOD - MAYBE AN OFF		**		
0001-0021142	1	note			BRAND LINING		**		
0001-0021142	1	note			RELINE REAR BRAKES		**		
0001-0021260	2	P 121803	013-000-000	0332002150	RELAY,TROLLEY	CHK N/A	4.0	40.980	163.920
0001-0021260	2	note			HEATER - BLOWING CIRCUIT BREAKERS		**		
0001-0021260	2	note			REWIRE HEATER CIRCUIT - ADDED HI & LOW CIRCUIT RELAYS		**		
0001-0021260	1	L 121803	026-250-000	N/A	ROAD CALL	RC 0015	1.0	35.000	35.000
0001-0021260	1	note			NO HEATER - ROAD CALL TO LTC		**		
0001-0021260	2	L 121803	013-000-000	N/A	HEATING/ALA CONDITIONING	CHK 0012	5.0	35.000	175.000
0001-0021260	2	P 121903	013-000-000	30055-40	BREAKER,40 AMP	CHK N/A	1.0	3.590	3.590
0001-0021260	2	note			HEATER - BLOWING CIRCUIT BREAKERS		**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROY PAGE: 20
 Veh: 0001-008

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE941MH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LEMiles > 244316.0

MO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0021260	2	note			REWIRE HEATER CIRCUIT - ADDED H1 & LOW CIRCUIT RELAYS		**		
0001-0021068	1	L 122603	022-200-000	N/A	MECHANICAL	CHK 0011	1.0	35.000	35.000
0001-0021068	1	note			Inspect lift for damage/worn components and assess for		**		
0001-0021068	1	note			continued serviceability.		**		
0001-0021068	1	note			INSPECTED BY MAYNARD - OK FOR CONTINUED USE		**		
0001-0021068	1	note			NO REPAIRS UNLESS LIFT MALLFUNCTIONS		**		
0001-0021335	1	P 122603	015-150-000	80205	HOSE, VACUUM	RPR N/A	2.0	0.150	0.300
0001-0021335	1	L 122603	015-150-000	N/A	WIPER BLADES AND WASHER	RPR 0006	0.5	35.000	17.500
0001-0021335	1	note			W/S WASHER HOSE ON THE CENTER WIPER IS SPLIT AT THE BASE		**		
0001-0021335	1	note			REPLACED HOSE		**		
0001-0021416	6	L 010704	010-360-000	N/A	LIGHTS-INTERIOR	RPR 0014	0.1	35.000	10.500
0001-0021416	6	note			CHARGE SYSTEM INOP LIGHT CAME ON COMING DOWN BAKERVLEW FOR A		**		
0001-0021416	6	note			FEW MINUTES THEN IT WENT BACK OFF		**		
0001-0021416	6	note			COULD NOT DUPLICATE		**		
0001-0021416	1	P 010804	025-200-000	4864JBR	ALTERNATOR, TROLLEY	PM N/A	1.0	339.050	339.050
0001-0021416	1	P 010804	025-200-000	3289056	BELT, SERP. TROLLEY OLD #	PM N/A	1.0	13.840	13.840
0001-0021416	1	P 010804	025-200-000	7161-5	WIRE, 2/0 BLACK	PM N/A	2.0	2.070	4.140
0001-0021416	4	L 010804	010-050-000	N/A	ALTERNATOR	RPL 0013	2.5	35.000	87.500
0001-0021416	4	L 010804	010-050-000	N/A	ALTERNATOR	RPL 0006	2.5	35.000	87.500
0001-0021416	4	L 011004	010-050-000	N/A	ALTERNATOR	RPL 0017	3.5	35.000	122.500
0001-0021416	4	note			ALT BAD/BELT - POOR GROUND CABLE - ROAD CALL		**		
0001-0021416	4	note			ALT BAD AGAIN - INSTALLED A 140 AMP LEECE-NEVILLE FROM MOTOR		**		
0001-0021416	4	note			TRUCK		**		
0001-0021416	1	P 011304	025-200-000	119555HD	ALTERNATOR, 130 AMP L/W	PM N/A	1.0	162.470	162.470
0001-0021416	1	P 011304	025-200-000	PMB98CC	KIT-CABLE CAR B-1998	PM N/A	1.0	0.000	0.000
0001-0021416	2	P 011304	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM N/A	1.0	8.259	8.259
0001-0021416	1	P 011304	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM N/A	1.0	6.812	6.812
0001-0021416	1	P 011304	025-200-000	LF3500	FILTER, OIL CUMMINS	PM N/A	1.0	18.399	18.399
0001-0021416	1	P 011304	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM N/A	1.0	7.500	7.500
0001-0021416	1	P 011304	025-200-000	3920773	WASHER, SEALING TROLLEY O	PM N/A	1.0	0.759	0.759
0001-0021416	1	P 011304	025-200-000	5C43B	FILTER, HEATER TROLLEY	PM N/A	1.0	5.330	5.330
0001-0021416	1	P 011304	025-200-000	PMB98CC	END-CABLE CAR B-1998	PM N/A	1.0	0.000	0.000
0001-0021416	1	P 011304	025-200-000	15W-40L	OIL, TOBEROOM TANK ONLY!!	PM N/A	25.0	0.820	20.500
0001-0021416	1	L 011304	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0017	8.0	35.000	280.000
0001-0021416	1	P 011404	025-200-000	81264	ROOT, TOGGLE	PM N/A	1.0	2.560	2.560
0001-0021416	1	P 011404	025-200-000	55019	SWITCH, TOGGLE ON-OFF-ON	PM N/A	1.0	5.450	5.450

DATE: 02/26/2006
 Time: 12:28 p.m.

WIAATCCM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 21
 Veh: 0001-308

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRN TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QUY	PRICE/WG	TOTAL COST
0001-0021416	1	L	011404	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0012	3.5	35.000	122.50
0001-0021416	3	L	011404	007-150-000	N/A	ENGINE START SOLENOID	RPL	0012	0.5	35.000	17.50
0001-0021416	3	note				ENGINE START SWITCH - REPLACED			**		
0001-0021416	5	P	011504	010-360-000	60419	LAMP,LIGHT DOME 6 IN. AL RPT.	N/A		2.0	8.540	17.08
0001-0021416	5	note				ENGINE COMPARTMENT LIGHT OUT			**		
0001-0021416	5	note				REPLACED WITH DIFF STYLE			**		
0001-0021426	2	L	011604	012-100-000	N/A	AIR COMPRESSOR TEST	CHK	0015	0.5	35.000	17.50
0001-0021416	5	I	011604	010-360-000	N/A	LIGHTS-INTERIOR	RPL	0015	1.5	35.000	52.50
0001-0021416	5	note				ENGINE COMPARTMENT LIGHT OUT			**		
0001-0021416	5	note				REPLACED WITH DIFF STYLE			**		
0001-0021416	4	P	011904	010-050-000	4B64JBR	ALTERNATOR,TROLLEY	RPL	N/A	1.0-	339.050	339.05
0001-0021416	4	note				ALT BAD/BELT - POOR GROUND CABLE - ROAD CALL			**		
0001-0021416	4	note				ALT BAD AGAIN - INSTALLED A 140 AMP LEECE-NEVILLE FROM MOTOR			**		
0001-0021416	4	note				TRUCK			**		
0001-0021601	2	I	011904	010-360-000	N/A	LIGHTS-INTERIOR	RPR	0014	0.5	35.000	17.50
0001-0021601	2	note				2 INTERIOR ROOF LIGHTS OUT			**		
0001-0021601	1	L	012004	010-650-000	N/A	RADIO/ANTENNA	CHK	0007	0.2	35.000	7.00
0001-0021601	1	note				BOTTOM OF DISPLAY ON RADIO - 3 DOUBLE DIGIT NUMBERS ACROSS			**		
0001-0021601	1	note				BOTTOM			**		
0001-0021601	1	note				REMOVED JUSTION KEY - TESTE OK			**		
0001-0021671	1	L	012704	024-000-000	N/A	TIRES, TUBES, LINERS	RPL	0014	0.5	35.000	17.50
0001-0021671	1	note				Valve stem on LH O/S dual is broken off			**		
0001-0021671	1	note				REPLACE WHEEL/TIRE			**		
0001-0021762	1	L	020404	026-250-000	N/A	ROAD CALL	RC	0011	1.0	35.000	35.00
0001-0021762	1	L	020404	026-250-000	N/A	ROAD CALL	RC	0012	1.0	35.000	35.00
0001-0021762	1	note				ROAD CALL TO LYNDEN TRANSIT CENTER - LEAKING OIL			**		
0001-0021762	1	note				WENT TO LYNDEN AND SWAPPED -BROUGHT COACH BACK TO SHOP			**		
0001-0021762	2	I	020404	007-000-000	N/A	ENGINE SYSTEM	CHK	0015	1.0	35.000	35.00
0001-0021762	2	P	020504	007-000-000	3914136	CAP,OIL FILLER B.JL TROL	CHK	N/A	1.0	2.630	2.63
0001-0021762	2	note				OIL FILLER CAP NOT ON			**		
0001-0021762	2	note				REPLACED CAP - CLEAN ENGINE AREA AND BACK OF BUS			**		
0001-0021821	1	L	023004	010-300-000	N/A	INDICATOR:GAUGE,METER,ET	RPR	0014	1.5	35.000	52.50
0001-0021821	1	P	021104	020-300-000	011005412	SENDER,OIL PRESURE	RPR	N/A	1.0	31.346	31.34
0001-0021821	1	note				Front oil pressure gauge is very irradic			**		
0001-0021821	1	note				TEST OIL SENDER TO FIND FRONT GAUGE SENDER - REPLACED			**		
0001-0021950	2	L	031904	012-000-000	N/A	AIR SYSTEM	RPL	0014	0.5	35.000	17.50

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROW PAGE: 22
Veh: 0001-008

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE041WB524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TYP	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0021950	2	note			REPLACE AIR FILTER ASSEMBLY				**		
0001-0021950	1	P	032204	025-300-000	AH1104	FILTER,AIR ASSY TROLLEY	PM	N/A	1.0	73.150	73.150
0001-0021950	1	P	032204	025-300-000	PMC98CC	KIT-CABLE CAR C-1998	PM	N/A	1.0	0.000	0.000
0001-0021950	1	P	032204	025-300-000	FS1000	FILTER,FUEL USE FOR ORTO	PM	N/A	1.0	8.260	8.260
0001-0021950	1	P	032204	025-300-000	FS1251	FILTER,FUEL TROLLEY	PM	N/A	1.0	6.840	6.840
0001-0021950	1	P	032204	025-300-000	LF3000	FILTER,OIL CUMMINS	PM	N/A	1.0	1.240	1.240
0001-0021950	1	P	032204	025-300-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM	N/A	2.0	7.500	15.000
0001-0021950	1	P	032204	025-300-000	29540493	FILTER,TRANS-ALLISON	PM	N/A	1.0	64.759	64.759
0001-0021950	1	P	032204	025-300-000	3920773	WASHER,SEALING TROLLEY	PM	N/A	1.0	0.759	0.759
0001-0021950	1	P	032204	025-300-000	5C438	FILTER,HEATER TROLLY	PM	N/A	1.0	5.330	5.330
0001-0021950	1	P	032204	025-300-000	PMC98CC	END-CABLE CAR C-1998	PM	N/A	1.0	0.000	0.000
0001-0021950	1	L	032204	025-300-000	N/A	PM C (12,000 & 36,000 MT	PM	0016	2.5	35.000	87.500
0001-0021950	3	L	032204	022-000-000	N/A	WHEELCHAIR LIFTS	RPR	0016	3.0	35.000	105.000
0001-0021950	3	L	032304	022-000-000	N/A	WHEELCHAIR LIFTS	RPR	0016	4.0	35.000	140.000
0001-0021950	3	note			REMOVE LIFT FOR REPAIR				**		
0001-0021950	6	L	032304	007-000-000	N/A	ENGINE SYSTEM	CHK	0016	4.0	35.000	140.000
0001-0021950	6	note			ENG OIL LEAK - REPLACED OUTER GASKET AND RETORQUE SEAL				**		
0001-0021950	6	note			HOUSING - TEST DRIVE AND RECHECK - ALL GOOD				**		
0001-0022273	1	OP	032304	015-200-000	SHAWMANEE	BODY REPAIR	OUT	N/A	1.0	4328.000	4328.000
0001-0022273	1	OP	032304	015-200-000	LFS	BODY REPAIR SUPPLIES	OUT	N/A	1.0	407.760	407.760
0001-0022273	1	note			ANNUAL WOOD WORKING REPAIR				**		
0001-0021950	1	P	032404	025-300-000	4025270	SEAL,FRT. COVER C8.3	PM	N/A	1.0	14.140	14.140
0001-0021950	1	P	032404	025-300-000	J917780	GASKET,COVER FRT. TROLLE	PM	N/A	1.0	17.620	17.620
0001-0021950	1	P	032404	025-300-000	3823494	SEALANT,GREY SILICONE	PM	N/A	1.0	8.500	8.500
0001-0021950	7	L	032404	007-200-000	N/A	EXHAUST SYSTEM	RPR	0016	1.5	35.000	52.500
0001-0021950	7	note			EXHAUST REPAIR				**		
0001-0021950	6	L	032404	007-000-000	N/A	ENGINE SYSTEM	CHK	0016	1.0	35.000	35.000
0001-0021950	6	note			ENG OIL LEAK - REPLACED OUTER GASKET AND RETORQUE SEAL				**		
0001-0021950	6	note			HOUSING - TEST DRIVE AND RECHECK - ALL GOOD				**		
0001-0021950	4	L	032404	013-100-000	N/A	WEBASTO HEATER	CHK	0016	1.0	35.000	35.000
0001-0021950	4	note			WEBASTO WOULD NOT STAY RUNNING AND HAS LOOSE EXHAUST				**		
0001-0021950	6	L	032404	007-000-000	N/A	ENGINE SYSTEM	CHK	0016	0.5	35.000	17.500
0001-0021950	6	note			ENG OIL LEAK - REPLACED OUTER GASKET AND RETORQUE SEAL				**		
0001-0021950	6	note			HOUSING - TEST DRIVE AND RECHECK - ALL GOOD				**		
0001-0021950	1	P	032504	025-300-000	030774402	MOUNT,RUBBER EAD/ENG. SU	PM	N/A	1.0	1.720	1.720
0001-0021950	3	P	032504	022-000-000	4851	TAPE,WEATHERSTRIP 1/8 X	RPR	N/A	1.0	18.620	18.620

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
NO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 23
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LDMiles > 244316.0

WO#	LN	TRN TYP DATE	VKRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QUY	PRICE/WG	TOTAL COST
0001-0021950	3	P 032504	022-000-000	1170003	CAPSCREW, 1/4-20 X 3/4 SS	RPR N/A	50.0	0.101	5.05
0001-0021950	3	P 032504	022-000-000	1174419	BOLT, CARRIAGE 1/4-20 X 3	RPR N/A	50.0	0.148	7.40
0001-0021950	3	P 032504	022-000-000	1174417	BOLT, CARRIAGE 1/4-20 X 1	RPR N/A	50.0	0.138	6.90
0001-0021950	3	P 032504	022-000-000	1171063	LOCKWASHER, 1/4 SS	RPR N/A	100.0	0.031	3.10
0001-0021950	3	P 032504	022-000-000	1170861	NYLOCK, 5/16-18 SS	RPR N/A	42.0	0.115	4.83
0001-0021950	3	P 032504	022-000-000	1171013	WASHER, FLAT 1/4 X 5/8 SS	RPR N/A	100.0	0.029	2.90
0001-0021950	3	P 032504	022-000-000	1170053	CAPSCREW, 5/16-18 X 3/4 S	RPR N/A	50.0	0.123	6.15
0001-0021950	3	P 032504	022-000-000	1171015	WASHER, FLAT 5/16 X 3/4 S	RPR N/A	100.0	0.040	4.00
0001-0021950	3	P 032504	022-000-000	1171065	LOCKWASHER, 5/16 SS	RPR N/A	100.0	0.026	2.60
0001-0021950	4	note		REMOVE LIFT FOR REPAIR			**		
0001-0021950	1	P 032504	025-300-000	15W-40L	OIL, LUBEROOM TARK ONLY!!	PM N/A	25.0	0.790	19.75
0001-0021950	1	L 032504	025-300-000	N/A	PM C (12,000 @ 36,000 MI	PM 0016	4.0	35.000	140.00
0001-0021950	1	L 032504	025-300-000	N/A	PM C (12,000 @ 36,000 MI	PM 0014	6.5	35.000	227.50
0001-0021950	4	P 032604	013-100-000	101-838	COIL, IGNITION 12VDC WEBB	CHK N/A	1.0	236.690	236.69
0001-0021950	4	note		WEBASTO WOULD NOT STAY RUNNING AND HAS LOOSE EXHAUST			**		
0001-0021950	5	P 032604	007-600-000	3925560	DAMPENER, VIBRATION CB. JL	RPL N/A	1.0	197.300	197.30
0001-0021950	5	note		ALTERNATOR BELT HAS OIL ON IT - CLEAN OR REPLACE			**		
0001-0021950	3	P 032604	022-000-000	1170001	CAPSCREW, 1/4-20 X 1/2 SS	RPR N/A	50.0	0.080	4.00
0001-0021950	3	P 032604	022-000-000	10222-02437	U-NUT, 1/4-20 BLACK PHOS	RPR N/A	50.0	0.195	9.75
0001-0021950	3	P 032604	022-000-000	19575	KIT, CAM FOLLOWER 1 CAM P	RPR N/A	4.0	55.490	221.96
0001-0021950	3	P 032604	022-000-000	19583	KIT, CAM FOLLOWER - RICON	RPR N/A	4.0	60.990	243.96
0001-0021950	3	P 032604	022-000-000	C-075	COLLAR, SHAFT 3/4" ID RIC	RPR N/A	2.0	1.198	2.39
0001-0021950	3	P 032604	022-000-000	19576	BEARING, BUSHING RICON 10	RPR N/A	2.0	2.750	5.50
0001-0021950	3	P 032604	022-000-000	F9-0089	PIN, LIFT RICON	RPR N/A	1.0	15.230	15.23
0001-0021950	3	note		REMOVE LIFT FOR REPAIR			**		
0001-0021950	4	L 032604	013-100-000	N/A	WEBASTO HEATER	CHK 0016	1.0	35.000	35.00
0001-0021950	4	note		WEBASTO WOULD NOT STAY RUNNING AND HAS LOOSE EXHAUST			**		
0001-0021950	3	J 032604	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	0.5	35.000	17.50
0001-0021950	3	note		REMOVE LIFT FOR REPAIR			**		
0001-0021950	1	P 032704	025-300-000	ATF	OIL, AUTOMATIC TRANSMISSI	PM N/A	17.0	0.900	15.30
0001-0021950	3	J 032704	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	4.5	35.000	157.50
0001-0021950	3	L 032904	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	3.5	35.000	122.50
0001-0021950	3	L 033004	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	8.0	35.000	280.00
0001-0021950	3	P 033104	022-000-000	13329	PIN, ROLL RICON CLUTCH	RPR N/A	1.0	0.900	0.90
0001-0021950	3	L 033104	022-000-000	N/A	WHEELCHAIR LIFTS	RPR 0016	6.0	35.000	210.00
0001-0021950	3	note		REMOVE LIFT FOR REPAIR			**		

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 24
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TRM	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0021950	6	I		033104	007-000-000	N/A	ENGINE SYSTEM	CHK	0016	0.5	35.000	17.500
0001-0021950	6	note					ENG OIL LEAK - REPLACED OUTER GASKET AND RETORQUE SEAL			**		
0001-0021950	6	note					HOUSING - TEST DRIVE AND RECHECK - ALL GOOD			**		
0001-0022386	1	I		040104	007-000-000	N/A	ENGINE SYSTEM	RPR	0016	0.5	35.000	17.500
0001-0022386	1	note					Throttle sometimes delays 5 seconds or more. Did it 3 or 4			**		
0001-0022386	1	note					times this morning.			**		
0001-0022386	1	note					CHECK OUT ONLY DID IT ONCE			**		
0001-0022386	2	L		040104	013-000-000	N/A	HEATING/AIR CONDITIONING	RPR	0016	0.5	35.000	17.500
0001-0022386	2	note					RH rear heater is leaking coolant			**		
0001-0022386	2	note					CHECK FOR LEAKS AND TIGHTENED CLAMPS			**		
0001-0022386	3	L		040104	018-000-000	N/A	DOORS & REMOVABLE PANELS	RPR	0016	1.0	35.000	35.000
0001-0022386	3	note					Rear door responds very. It opens slowly about 1/2 way then			**		
0001-0022386	3	note					moves even slower the rest of the way. Sometimes there is a			**		
0001-0022386	3	note					10 second delay before door starts to close also			**		
0001-0022386	3	note					ADJUSTED DOOR SPEED			**		
0001-0022386	4	L		040104	010-350-000	N/A	LIGHTS/CLEARANCE, SKIRT, S	RPR	0016	0.3	35.000	10.500
0001-0022386	4	note					2 clearance lights are out			**		
0001-0022386	4	note					REPLACED LIGHTS			**		
0001-0022386	5	L		040104	016-000-000	N/A	INTERIOR PANELS & SPECIA	RPL	0016	0.2	35.000	7.000
0001-0022386	5	P		040204	016-000-000	011692502	MIRROR, 12" CONVEX	RPL	N/A	1.0	46.440	46.440
0001-0022386	5	note					Interior convex mirror is broken			**		
0001-0022386	5	note					REPLACED MIRROR			**		
0001-0022386	6	L		040204	008-100-000	N/A	RADIATOR SYSTEM	RC	0011	1.0	35.000	35.000
0001-0022386	6	L		040204	008-100-000	N/A	RADIATOR SYSTEM	RC	0012	2.0	35.000	70.000
0001-0022386	6	note					OVERHEADT - MADE COACH SWAP AT FERNDALE			**		
0001-0022386	6	note					CLEANED RADIATOR			**		
0001-0022386	7	OP		040504	015-000-000	JCM LOPEZ	BODY REPAIR	OUT	N/A	1.0	151.480	151.480
0001-0022386	7	note					REPAIR BY JON LOPEZ			**		
0001-0022386	8	P		040604	022-000-000	F9-0101	RAIL, GUIDE RICON MIRAGE	OTH	N/A	2.0	167.830	335.660
0001-0022386	8	P		040604	022-000-000	15952	NUT, SPRING RICON BAG OF	OTH	N/A	4.0	8.800	35.200
0001-0022386	8	note					PARTS FROM LAST MONTH (MARCH) REBUILT			**		
0001-0022412	1	P		040504	007-000-000	225B-601BA	VALVE, ELECTRIC/AIR	CHK	N/A	1.0	42.120	42.120
0001-0022412	1	L		040604	007-000-000	N/A	ENGINE SYSTEM	CHK	0017	2.0	35.000	70.000
0001-0022412	1	note					NO THROTTLE			**		
0001-0022412	1	note					REPLACED MAC VALVE			**		
0001-0022546	1	P		041904	010-350-000	52892-3	LAMP, SEALED MODEL 60	RPL	N/A	1.0	5.990	5.990

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 25
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TYP	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0022546	1	L	041904	010-350-000	N/A	LIGHTS/CLEARANCE,SKIRT,S	RPL 0006	0.3	35.000	10.500
0001-0022546	1	note			Center brake light is out			**		
0001-0022546	1	note			REPLACED LIGHT ASSMBY			**		
0001-0022546	2	P	041904	010-150-000	44710	FLASHER,12V 20 LAMP 45AM	RPR N/A	1.0	16.147	16.147
0001-0022546	2	L	041904	010-150-000	N/A	FLASHERS FUSES,CIRCUIT	RPR 0006	0.2	35.000	7.000
0001-0022546	2	note			4-ways and turn signal flasher sometimes skips a beat then			**		
0001-0022546	2	note			continues on.			**		
0001-0022546	2	note			REPLACED FLASHER			**		
0001-0022685	1	P	050404	010-150-000	011003044	DIODE,SAME AS PHILIPS EC	CHK N/A	1.0	2.240	2.240
0001-0022685	1	L	050404	010-150-000	N/A	FLASHERS FUSES,CIRCUIT	CHK 0013	2.0	35.000	70.000
0001-0022685	1	note			FOUR WAY FLASHER WORK LEFT SIDE ONLY			**		
0001-0022685	1	note			TRACED AND LOCATED BURNED DIODE - WIRE - REPLACED - REPAIRED			**		
0001-0022740	5	L	050804	010-350-000	N/A	LIGHTS/CLEARANCE,SKIRT,S	RPR 0013	0.3	35.000	10.500
0001-0022740	5	note			THE AMBER TURN SIGNAL LIGHT DIRECTLY BEHIND THE LEFT SIDE			**		
0001-0022740	5	note			DUALS IS OUT			**		
0001-0022707	1	L	051004	019-000-000	N/A	WINDOWS/GLASS	RPR 0004	2.5	35.000	87.500
0001-0022707	1	note			Report of a water leak at the base of the right front corner			**		
0001-0022707	1	note			of the cupola.WAS ABLE TO DUPLICATE WATER LEAK BY SPRAYING			**		
0001-0022707	1	note			WATER ON RF CUPOLA-RECAULKED SUSPECT AREAS OF CAULKING ABOVE			**		
0001-0022707	1	note			LEAKING SEAM, RETESTED OK (THIS LEAK HAS A LONG HISTORY AND			**		
0001-0022707	1	note			MAY HAVE BEEN RECAULKED BEFORE)			**		
0001-0022707	2	L	051004	021-000-000	N/A	FARE BOXES	RPR 0011	0.5	35.000	17.500
0001-0022707	2	note			Clean pass reader.			**		
0001-0022707	2	note			CLEANED PASS READER AND CHECKED OUT PASSES			**		
0001-0022740	1	P	051204	025-200-000	PME98CC	KIT-CABLE CAR E-1998	PM N/A	1.0	0.000	0.000
0001-0022740	1	P	051204	025-200-000	FS1000	FILTER,FUEL USE FOR ORIO	PM N/A	1.0	8.260	8.260
0001-0022740	1	P	051204	025-200-000	FS1251	FILTER,FUEL TROLLEY	PM N/A	1.0	6.840	6.840
0001-0022740	1	P	051204	025-200-000	LF3000	FILTER,OIL CUMMINS	PM N/A	1.0	12.897	12.897
0001-0022740	2	P	051204	025-200-000	CC2610	CLEANER,RAD FLUSH "RESTO	PM N/A	1.0	13.060	13.060
0001-0022740	1	P	051204	025-200-000	BF932	FILTER,WEBASTO	PM N/A	1.0	1.880	1.880
0001-0022740	1	P	051204	025-200-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM N/A	2.0	7.500	15.000
0001-0022740	1	P	051204	025-200-000	29540491	FILTER,TRANS.AJLJSON	PM N/A	1.0	64.749	64.749
0001-0022740	1	P	051204	025-200-000	C8016552	FILTER,HYDEAULIC,STEERIN	PM N/A	3.0	10.350	30.900
0001-0022740	1	P	051204	025-200-000	107794X	CARTRIDGE,AIR DRYER AD9	PM N/A	1.0	22.209	22.209
0001-0022740	1	P	051204	025-200-000	3920773	WASHER,SEALING TROLLEY	PM N/A	1.0	1.420	1.420
0001-0022740	1	P	051204	025-200-000	5C438	FILTER,HEATER TROLLEY	PM N/A	1.0	5.330	5.330

DATE: 02/16/2008
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
NO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 26
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47G30C LtMiles > 244316.0

WQI	LN	TRM TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0022740	1	P	051204	025-200-000	PME98CC	END-CABLE CAR E-1998	PM	N/A	1.0	0.000	0.00
0001-0022740	1	P	051204	025-200-000	PME98CC	KIT-CABLE CAR E-1998	PM	N/A	1.0-	0.000	0.00
0001-0022740	1	P	051204	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM	N/A	1.0-	8.260	8.26
0001-0022740	1	P	051204	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM	N/A	1.0-	6.840	6.84
0001-0022740	1	P	051204	025-200-000	LF3000	FILTER, OIL CUMMINS	PM	N/A	1.0-	12.897	12.89
0001-0022740	1	P	051204	025-200-000	CC2610	CLEANER, RAD FLOSH "RESTO	PM	N/A	1.0-	13.060	13.06
0001-0022740	1	P	051204	025-200-000	BF932	FILTER, WEBASTO	PM	N/A	1.0-	1.880	1.88
0001-0022740	1	P	051204	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM	N/A	2.0-	7.500	15.00
0001-0022740	1	P	051204	025-200-000	29540493	FILTER, TRANS. ALLISON	PM	N/A	1.0-	64.749	64.74
0001-0022740	1	P	051204	025-200-000	C8016552	FILTER, HYDRAULIC, STEERING	PM	N/A	1.0-	10.300	30.90
0001-0022740	1	P	051204	025-200-000	107794X	CARTRIDGE, AIR DRYER AD9	PM	N/A	1.0-	22.209	22.20
0001-0022740	1	P	051204	025-200-000	3920773	WASHER, SEALING TROLLEY O	PM	N/A	1.0-	1.420	1.42
0001-0022740	1	P	051204	025-200-000	5C438	FILTER, HEATER TROLLY	PM	N/A	1.0-	5.330	5.33
0001-0022740	1	P	051204	025-200-000	PME98CC	END-CABLE CAR E-1998	PM	N/A	1.0-	0.000	0.00
0001-0022740	1	P	051204	025-200-000	PMB98CC	KIT-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.00
0001-0022740	1	P	051204	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM	N/A	1.0	8.260	8.26
0001-0022740	1	P	051204	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM	N/A	1.0	6.840	6.84
0001-0022740	1	P	051204	025-200-000	LF3000	FILTER, OIL CUMMINS	PM	N/A	1.0	12.897	12.89
0001-0022740	1	P	051204	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM	N/A	1.0	7.500	7.50
0001-0022740	1	P	051204	025-200-000	3920773	WASHER, SEALING TROLLEY O	PM	N/A	1.0	1.420	1.42
0001-0022740	1	P	051204	025-200-000	5C438	FILTER, HEATER TROLLY	PM	N/A	1.0	5.330	5.33
0001-0022740	1	P	051204	025-200-000	PMB98CC	END-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.00
0001-0022740	1	P	051204	025-200-000	5902	GUARD, WHEEL TROLLEY	PM	N/A	2.0	2.025	4.05
0001-0022740	1	P	051204	025-200-000	15W-40L	OIL, LUBEROOM TANK ONLY!!	PM	N/A	25.0	0.792	19.80
0001-0022740	1	L	051204	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0004	8.0	35.000	280.00
0001-0022740	1	L	051204	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0013	5.2	35.000	182.00
0001-0022740	4	L	051204	008-100-000	N/A	RADIATOR SYSTEM	RPR	0013	2.0	35.000	70.00
0001-0022740	4	note			R/R RADIATOR TO CLEAN DIRT			**			
0001-0022740	3	P	051204	024-410-000	TIRE	TIRE	RPL	N/A	4.0	369.210	1476.92
0001-0022740	3	L	051204	024-410-000	N/A	TIRE REPLACE/REAR/RECAP	RPL	0013	0.8	35.000	28.00
0001-0022740	3	note			REPLACED TIRES			**			
0001-0022740	2	P	051204	024-300-000	TIRE	TIRE	RPL	N/A	2.0	369.330	738.66
0001-0022740	2	L	051204	024-300-000	N/A	TIRE REPLACE/Front/NEW	RPL	0013	0.5	35.000	17.50
0001-0022740	2	note			REPLACED TIRES			**			
0001-0022740	1	P	051304	025-200-000	68854	COCK, DRAIN 1/4"	PM	N/A	1.0	0.850	0.85
0001-0022740	1	P	052304	025-200-000	CT450L	CLAMP, CONSTANT TORQUE	PM	N/A	1.0	4.400	4.40

DATE: 02/16/2006
Time: 12:38 p.m.

WIDATCOM TRANSPORTATION
NO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/RCV PAGE: 27
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WE52412G Odom > 244376.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 476JUC LEMiles > 244316.0

WC#	TRN		LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
	LN	TYP											
0001-0022740	1	P	051304	025-200-000	8C064		HOSE, FUEL/WATER 3/8	PM	N/A	2.0	0.639	1.27	
0001-0022740	1	P	051304	025-200-000	705-3227		CLAMP, HOSE 3/8 FUEL LINE	PM	N/A	3.0	0.590	1.77	
0001-0022740	1	P	051304	025-200-000	8C064		HOSE, FUEL/WATER 3/8	PM	N/A	2.5	0.639	1.59	
0001-0022740	1	P	051304	025-200-000	78225GL		HOSE, SILICONE 2-1/4"	PM	N/A	10.0	1.584	15.84	
0001-0022740	1	P	051304	025-200-000	CT300L		CLAMP, CONSTANT TORQUE	PM	N/A	2.0	3.931	7.86	
0001-0022740	4	L	051304	008-100-000	N/A		RADIATOR SYSTEM	RPR	0013	4.0	35.000	140.00	
0001-0022740	4	L	051304	008-100-000	N/A		RADIATOR SYSTEM	RPR	0004	8.0	35.000	280.00	
0001-0022740	4	note					R/R RADIATOR TO CLEAN DIRT			**			
0001-0022796	1	L	051704	021-000-000	N/A		FARE BOXES	CHK	0011	0.7	35.000	24.50	
0001-0022796	1	note					RED DOT INSPECTION			**			
0001-0022740	1	P	051804	025-200-000	Q347137		DIPSTICK, HYD. P/S RESERV	PM	N/A	1.0	6.960	6.96	
0001-0022812	1	L	051804	020-200-000	N/A		OTHER SEATS	OUT	0014	0.5	35.000	17.50	
0001-0022812	1	OP	051804	020-200-000	CRAWFORD		SEAT REPAIR	OUT	N/A	1.0	81.150	81.15	
0001-0022812	1	note					Rear seat cushion has a couple of cuts, about 3" long			**			
0001-0023071	3	L	061004	026-250-000	N/A		ROAD CALL	RC	0011	2.0	35.000	70.00	
0001-0023071	3	L	061004	026-250-000	N/A		ROAD CALL	RC	0013	2.0	35.000	70.00	
0001-0023071	3	note					ROAD CALL TO FERDALE			**			
0001-0023071	3	note					NO POWER STEERING			**			
0001-0023071	1	P	061404	016-000-000	3978340		GASKET, AIR COMP MPN TROL	CHK	N/A	1.0	8.330	8.33	
0001-0023071	1	P	061404	016-000-000	C8019002		PUMP, HYD P/S TROLLEY	CHK	N/A	1.0	648.880	648.88	
0001-0023071	1	P	061404	016-000-000	154916		GASKET, PUMP MOUNTING	CHK	N/A	1.0	2.251	2.25	
0001-0023071	1	P	061404	016-000-000	3558051RX		COMPRESSOR, RX 15CFM TROL	CHK	N/A	1.0	686.500	686.50	
0001-0023071	1	P	061404	016-000-000	C8016552		FILTER, HYDRAULIC, STEERIN	CHK	N/A	3.0	13.073	39.21	
0001-0023071	1	P	061404	016-000-000	HTF		OIL, HYD. FOR TROLLEY 5 G	CHK	N/A	2.0	38.860	77.72	
0001-0023071	1	note					Operator reports: The flooring material over the left rear			**			
0001-0023071	1	note					wheel well is split along the aisle edge and rear edge. Rain			**			
0001-0023071	1	note					water is sprayed up thru the split and onto the floor			**			
0001-0023071	1	note					inside. I have checked on three different rainy days and			**			
0001-0023071	1	note					can't find another source like dripping wet passengers or a			**			
0001-0023071	2	L	061404	021-000-000	N/A		FARE BOXES	CHK	0007	0.2	35.000	7.00	
0001-0023071	2	note					Operator reports: Farebox bill transport is jammed.			**			
0001-0023071	2	note					REPLACED BILL TRANSPORT			**			
0001-0023071	4	L	061404	011-000-000	N/A		HYDRAULIC SYSTEM	RPR	0009	7.0	35.000	105.00	
0001-0023071	4	L	061404	011-000-000	N/A		HYDRAULIC SYSTEM	RPR	0018	9.0	35.000	315.00	
0001-0023071	4	note					WASHED BUS AFTER HYD PUMP			**			
0001-0023071	4	note					REPLACED THROTTLE LINKAGE REMOUNTED DIPSTICK AND AIR INTAKE			**			

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROV PAGE: 28
 Veh: 000T-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C L/Miles > 244316.0

WO#	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0023071	4	note				DIAG AND REPAIR FAN SWITCH			**		
0001-0023071	4	note				REPLACED AIR COMPRESSOR AND HYD PUMP - STEAM CLEAN NEED TO			**		
0001-0023071	4	note				TEST AND CHECK FOR LEAKS			**		
0001-0023071	1	P	061504	016-000-000	115-007	END, THROTTLE ROD TROLLEY CHK	N/A		1.0	7.120	7.120
0001-0023071	1	P	061504	016-000-000	3103015	SLEEVE, RUBBER COMPR. WAT CHK	N/A		3.0	0.880	2.640
0002-0023071	1	note				Operator reports: The flooring material over the left rear			**		
0003-0023071	1	note				wheel well is split along the aisle edge and rear edge. Rain			**		
0001-0023071	1	note				water is sprayed up threw the split and onto the floor			**		
0001-0023071	1	note				inside. I have checked on three different rainy days and			**		
0001-0023071	1	note				can't find another source like dripping wet passengers or a			**		
0001-0022925	1	L	061604	015-200-000	N/A	BODY REPAIR/INCIDENTAL	RPR 0007		0.7	35.000	24.500
0001-0022925	1	note				Body damage and wood loose above streetside front turn			**		
0001-0022925	1	note				signal lamp.			**		
0001-0022925	1	note				SERVICEABLE REPAIR			**		
0001-0023071	1	L	061604	016-000-000	N/A	INTERIOR PANELS & SPECIA	CHK 0007		0.5	35.000	17.500
0001-0023071	1	note				Operator reports: The flooring material over the left rear			**		
0001-0023071	1	note				wheel well is split along the aisle edge and rear edge. Rain			**		
0001-0023071	1	note				water is sprayed up threw the split and onto the floor			**		
0001-0023071	1	note				inside. I have checked on three different rainy days and			**		
0001-0023071	1	note				can't find another source like dripping wet passengers or a			**		
0001-0023172	1	L	062204	005-200-000	N/A	RELINE, REAR	CHK 0013		1.0	35.000	35.000
0001-0023172	1	note				SEEM TO HAVE TO PRESS MUCH HARDER ON BRAKE PEDAL TO BRAKE			**		
0001-0023172	1	note				WELL			**		
0001-0023172	1	note				REAR RELINE			**		
0001-0023172	1	note				BRAKE PEDAL SEEMS FINE TO ME - BOWMONK 74/23			**		
0001-0023172	2	P	062404	025-200-000	PMB950B	KIT-ORION B-1995	PM N/A		1.0	0.000	0.000
0001-0023172	2	P	062404	025-200-000	FS1000	FILTER, FUEL USE FOR OR10	PM N/A		1.0	8.260	8.260
0001-0023172	2	P	062404	025-200-000	LF3000	FILTER, OIL CUMMINS	PM N/A		1.0	17.443	17.443
0001-0023172	2	P	062404	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM N/A		1.0	7.500	7.500
0001-0023172	2	P	062404	025-200-000	6794G	GASKET, DRAIN PLUG, OIL PA	PM N/A		1.0	0.979	0.979
0001-0023172	2	P	062404	025-200-000	2122K153	FILTER, ORION HTR*SELL EA	PM N/A		1.0	0.975	0.975
0001-0023172	2	P	062404	025-200-000	PMB950B	END-ORION B-1995	PM N/A		1.0	0.000	0.000
0001-0023172	2	P	062404	025-200-000	PMB950B	KIT-ORION B-1995	PM N/A		1.0	0.000	0.000
0001-0023172	2	P	062404	025-200-000	FS1000	FILTER, FUEL USE FOR OR10	PM N/A		1.0	8.260	8.260
0001-0023172	2	P	062404	025-200-000	LF3000	FILTER, OIL CUMMINS	PM N/A		1.0	17.443	17.443
0001-0023172	2	P	062404	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM N/A		1.0	7.500	7.500

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 29
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841W6524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LEMiles > 244316.0

WO#	LN	TRN TYP DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0023172	2	P 062404	025-200-000	67946	GASKET, DRAIN PLOG, OIL PA	PM N/A	1.0-	0.979	0.97
0001-0023172	2	P 062404	025-200-000	2122K151	FILTER, ORION HTR*SELL EA	PM N/A	1.0-	0.975	0.97
0001-0023172	2	P 062404	025-200-000	PMB950B	END-ORION B-1995	PM N/A	1.0-	0.000	0.00
0001-0023172	2	P 062404	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM N/A	1.0	8.260	8.26
0001-0023172	2	P 062404	025-200-000	LF3000	FILTER, OIL CUMMINS	PM N/A	1.0	17.443	17.44
0001-0023172	2	P 062404	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM N/A	3.0	6.840	6.84
0001-0023172	2	P 062404	025-200-000	67946	GASKET, DRAIN PLOG, OIL PA	PM N/A	1.0	0.979	0.97
0001-0023172	2	P 062404	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM N/A	1.0	7.500	7.50
0001-0023172	1	P 062404	005-200-000	KIT6115ACL	SHOE, KIT TROLLEY REAR W/	CHK N/A	2.0	171.260	342.52
0001-0023172	1	P 062404	005-200-000	85123365002	DRUM, REAR TROLLEY	CHK N/A	2.0	93.770	187.54
0001-0023172	1	note			SEEM TO HAVE TO PRESS MUCH HARDER ON BRAKE PEDAL TO BRAKE		**		
0001-0023172	1	note			WELL		**		
0001-0023172	1	note			REAR RELINE		**		
0001-0023172	1	note			BRAKE PEDAL SEEMS FINE TO ME - BOWMONK 74/23		**		
0001-0023172	2	L 062404	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0015	2.0	35.000	70.00
0001-0023172	2	L 062404	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0009	6.5	35.000	227.50
0001-0023172	2	L 062404	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0009	1.0	35.000	35.00
0001-0023172	7	L 062404	007-000-000	N/A	ENGINE SYSTEM	CHK 0009	0.2	35.000	7.00
0001-0023172	7	note			THROTTLE RETURN SPRING		**		
0001-0023172	1	P 062504	005-200-000	13-3052	NUT, LUG METRIC TROLLEY	CHK N/A	20.0	2.167	43.34
0001-0023172	1	P 062504	005-200-000	13-7208	WEDGE, HUB TROLLEY	CHK N/A	24.0	1.024	24.57
0001-0023172	1	P 062504	005-200-000	13-3052	NUT, LUG METRIC TROLLEY	CHK N/A	20.0-	2.167	43.34
0001-0023172	1	P 062504	005-200-000	13-7110	GASKET, AXLE, BEAR (CABLE	CHK N/A	2.0	0.697	1.39
0001-0023172	1	P 062504	005-200-000	370023A	SEAL, REAR AXLE TROLLEY	CHK N/A	2.0	28.570	57.14
0001-0023172	1	note			SEEM TO HAVE TO PRESS MUCH HARDER ON BRAKE PEDAL TO BRAKE		**		
0001-0023172	1	note			WELL		**		
0001-0023172	1	note			REAR RELINE		**		
0001-0023172	1	note			BRAKE PEDAL SEEMS FINE TO ME - BOWMONK 74/23		**		
0001-0023172	2	P 062504	025-200-000	575066C1	SPRING, THROTTLE RETURN, T	PM N/A	1.0	4.100	4.10
0001-0023172	1	P 062504	005-200-000	13-3052	NUT, LUG METRIC TROLLEY	CHK N/A	20.0	2.167	43.34
0001-0023172	1	L 062504	005-200-000	N/A	RELINE, REAR	CHK 0015	7.0	35.000	245.00
0001-0023172	1	L 062504	005-200-000	N/A	RELINE, REAR	CHK 0009	1.0	35.000	35.00
0001-0023172	1	note			SEEM TO HAVE TO PRESS MUCH HARDER ON BRAKE PEDAL TO BRAKE		**		
0001-0023172	1	note			WELL		**		
0001-0023172	1	note			REAR RELINE		**		
0001-0023172	1	note			BRAKE PEDAL SEEMS FINE TO ME - BOWMONK 74/23		**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WC TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: 3-412/ROV PAGE: 30
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > IC9VTE841WU524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAB Lic. Plate > 47630C LtMiles > 244316.0

WO#	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QUY	PRICE/WG	TOTAL COST
0001-0023172	2	L	062504	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0009	3.0	35.000	105.000
0001-0023172	4	L	062504	016-000-000	N/A	INTERIOR PANELS & SPECIA	RPR 0009	3.0	35.000	105.000
0001-0023172	4	note			HANDRAIL REPAIRS/FENDER REPAIRS		**			
0001-0023172	5	L	062504	013-100-000	N/A	WEBASTO HEATER	CHK 0018	1.0	35.000	35.000
0001-0023172	5	note			WEBASTO WILL NOT FIRE - PART HERE		**			
0001-0023172	6	L	062504	010-360-000	N/A	LIGHTS-INTERIOR	CHK 0018	0.5	35.000	17.500
0001-0023172	7	L	062504	007-000-000	N/A	ENGINE SYSTEM	CHK 0018	0.5	35.000	17.500
0001-0023172	7	note			THROTTLE RETURN SPRING		**			
0001-0023172	4	P	062804	016-000-000	HBR011	BRACKET,HANDRAIL TROLLEY RPR	N/A	1.0	16.500	16.500
0001-0023172	4	note			HANDRAIL REPAIRS/FENDER REPAIRS		**			
0001-0023172	3	L	062804	012-100-000	N/A	AIR COMPRESSOR TEST	CHK 0009	0.2	35.000	7.000
0001-0023172	5	P	062904	013-100-000	287.962	CONTROL,12V TROLLEY RED	CHK N/A	1.0	305.470	305.470
0001-0023172	5	L	062904	013-100-000	N/A	WEBASTO HEATER	CHK 0017	1.0	35.000	35.000
0001-0023172	5	note			WEBASTO WILL NOT FIRE - PART HERE		**			
0001-0023546	2	L	071904	010-650-000	N/A	RADIO/ANTENNA	CHK 0007	0.7	35.000	24.500
0001-0023546	2	note			AM/FM NOT WORKING		**			
0001-0023546	2	note			NO REPAIR - RADIO BAD		**			
0001-0023546	1	L	072904	016-000-000	N/A	INTERIOR PANELS & SPECIA	CHK 0011	0.3	35.000	10.500
0001-0023546	1	note			Operator reports: The last vertical pull cord for the bell		**			
0001-0023546	1	note			on the left side has detached at the bottom.		**			
0001-0023546	1	note			REINSTALLED BELL CORD		**			
0001-0023639	1	L	080904	009-100-000	N/A	FUEL TANK ASSEMBLY	CHK 0009	2.0	35.000	70.000
0001-0023639	1	note			FUEL LEAK AT TANK		**			
0001-0023639	1	note			DIAGNOSE FUEL LEAK, CLEAN TANK, RECHECK W/TEST DIRVE - LEAK		**			
0001-0023639	1	note			WAS FROM WISTLE - PROBABLY OVER FILLED TANK		**			
0001-0023724	1	P	081604	008-000-000	STD351	LINE,BRAKE STEEL 3/16X51	RPR N/A	1.0	2.780	2.780
0001-0023724	1	L	081604	008-000-000	N/A	COOLING SYSTEM	RPR 0011	1.5	35.000	52.500
0001-0023724	1	note			Operator reports overhear.		**			
0001-0023724	1	note			BLEW ALOT OF DIRT AND DEBRIS FROM RADIATOR AND CHARGE AIR		**			
0001-0023724	1	note			COOLER - ROAD TESTED AND COULD NOT MAKE ENGINE OVERHEAT		**			
0001-0023879	1	L	082704	018-000-000	N/A	DOORS & REMOVABLE PANELS	CHK 0011	0.5	35.000	17.500
0001-0023879	1	note			Operator reports: Back door closes fifty percent of the		**			
0001-0023879	1	note			time.		**			
0001-0023879	1	note			CHECKED DOOR OPEATION SEVERAL TIMES IN BOTH DIRECTION WITH		**			
0001-0023879	1	note			THE CONTROL HANDLE AND COULD NOT DUPLICATE THIS PROBLEM		**			
0001-0023937	1	L	090204	026-250-000	N/A	ROAD CALL	CHK 0006	1.0	35.000	35.000

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
NO TRANSACTION RET BY VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROW PAGE: 31
Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9WTEB41WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C Lfmiles > 244316.0

WO#	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0023937	1	L	090204	026-250-000	N/A	ROAD CALL	CHK	0018	1.0	35.000	35.000
0001-0023937	1	note				Road call to Ferndale, coach swap.			**		
0001-0023937	2	L	090204	017-200-000	N/A	CONTROLS	CHK	0011	1.5	35.000	52.500
0001-0023937	2	note				Operator reports: Transmission is shifting erratically, and			**		
0001-0023937	2	note				is now stuck in second gear. COULD NOT DUPLICATE TRANS			**		
0001-0023937	2	note				SHIFTING PROBLEM - FOUND ONE INACTIVE CODE THAT HAD ONE			**		
0001-0023937	2	note				COUNT - CHECKED ITEMS ON LIST OF POSSIBLE CAUSES FOR CODE			**		
0001-0023937	2	note				AND FOUND NOTHING WRONG-ERASED CODE AND ROAD TESTED			**		
0001-0023924	1	P	090304	025-400-000	EMD98CC	KIT-CABLE CAR D-1998	PM	N/A	1.0	0.000	0.000
0001-0023924	1	P	090304	025-400-000	FS1000	FILTER, FUEL USE FOR ORIO	PM	N/A	1.0	8.636	8.636
0001-0023924	1	P	090304	025-400-000	FS1251	FILTER, FUEL TROLLEY	PM	N/A	1.0	7.105	7.105
0001-0023924	1	P	090304	025-400-000	LF3000	FILTER, OIL CUMMINS	PM	N/A	1.0	18.581	18.581
0001-0023924	1	P	090304	025-400-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM	N/A	2.0	7.500	15.000
0001-0023924	1	P	090304	025-400-000	29540493	FILTER, TRANS. ALLISON	PM	N/A	1.0	64.740	64.740
0001-0023924	1	P	090304	025-400-000	107794X	CARTRIDGE, AIR DRYER AD9	PM	N/A	1.0	22.039	22.039
0001-0023924	1	P	090304	025-400-000	3920773	WASHER, SEALING TROLLEY O	PM	N/A	1.0	1.713	1.713
0001-0023924	1	P	090304	025-400-000	5C438	FILTER, HEATER TROLLY	PM	N/A	1.0	5.330	5.330
0001-0023924	1	P	090304	025-400-000	PM098CC	END-CABLE CAR D-1998	PM	N/A	1.0	0.000	0.000
0001-0023924	1	P	090304	025-400-000	107794X	CARTRIDGE, AIR DRYER AD9	PM	N/A	1.0	22.039	22.039
0001-0023924	1	P	090304	025-400-000	15W-40L	OIL, LUBEROOM TANK ONLY!!	PM	N/A	25.0	0.783	19.575
0001-0023924	1	P	090304	025-400-000	ATF	OIL, AUTOMATIC TRANSMISSI	PM	N/A	17.0	0.895	15.215
0001-0023924	1	P	090304	025-400-000	80W-90	OIL, GEAR LUBE 410W DRUM	PM	N/A	17.0	1.019	17.323
0001-0023924	1	L	090304	025-400-000	N/A	PM D - ORION (24,000 MI)	PM	0004	7.5	35.000	262.500
0001-0023924	1	L	090404	025-400-000	N/A	PM D - ORION (24,000 MI)	PM	0013	4.0	35.000	140.000
0001-0023924	1	P	090704	025-400-000	3804883RX	PUMP, WATER " C" TROLLEY	PM	N/A	1.0	88.750	88.750
0001-0023924	1	J	090704	025-400-000	N/A	PM D - ORION (24,000 MI)	PM	0009	8.0	35.000	280.000
0001-0023924	1	L	090704	025-400-000	N/A	PM D - ORION (24,000 MI)	PM	0013	1.5	35.000	52.500
0001-0023924	1	L	090704	025-400-000	N/A	PM D - ORION (24,000 MI)	PM	0016	0.5	35.000	17.500
0001-0023924	5	L	090704	022-000-000	N/A	WHEELCHAIR LIFTS	RPR	0013	1.0	35.000	35.000
0001-0023924	5	note				WHEELCHAIR LIFT ADJUSTMENT			**		
0001-0023924	4	L	090704	018-000-000	N/A	DOORS & REMOVABLE PANELS	CHK	0016	0.5	35.000	17.500
0001-0023924	4	note				REAR DOOR EDGE-REAR MIRRO - SEAT CUSHION			**		
0001-0023924	3	L	090704	013-100-000	N/A	WEBASTO HEATER	CHK	0013	1.0	35.000	35.000
0001-0023924	3	note				WEBASTO INOP			**		
0001-0023924	3	note				WEBASTO EXHAUST BROKEN			**		
0001-0023924	2	P	090704	008-300-000	ANTIFREEZER	COOLANT, EXTEND SERV. 55G	CHK	N/A	20.0	1.146	22.920

DATE: 02/16/2006
 Time: 12:18 p.m.

WILATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

JD: J-412/ROV PAGE: 32
 Veb: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTEB41WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C Lf Miles > 244316.0

WCA	LN	TRN TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QT	PRICE/WG	TOTAL COST
0001-0023924	2	I	090704	008-300-000	N/A	WATER PUMP ASSEMBLY	CHK	0013	4.5	35.000	157.500
0001-0023924	2	P	091004	008-300-000	SV404P-12-8	VALVE, TRUCK	CHK	N/A	1.0	19.570	19.570
0001-0023924	2	P	091004	008-300-000	V405P-8-8	VALVE, GATE TROLLEY	CHK	N/A	1.0	13.230	13.230
0001-0023924	2	note			REPLACED WATER PUMP				**		
0001-0023924	2	note			DRILL OUT BROKEN BOLT				**		
0001-0023924	2	note			INSTALLED ANTIFREEZE				**		
0001-0024234	3	L	100604	010-350-000	N/A	LIGHTS/CLEARANCE, SKIRT, S	RPR	0006	0.3	35.000	10.500
0001-0024234	3	note			MARKER LAMP OUT ON THE TOP RIGHT FRONT				**		
0001-0024234	3	note			REPLACED (2) BULBS				**		
0001-0024234	1	P	100804	010-150-000	5589	SWITCH, TOGGLE	RPS	N/A	1.0	4.715	4.715
0001-0024234	1	L	100804	010-150-000	N/A	FLASHERS FUSES, CIRCUIT	RPR	0006	0.5	35.000	17.500
0001-0024234	1	note			4 way flashers don't work on RH side				**		
0001-0024234	1	note			REPLACED 4-WAY SWITCH				**		
0001-0024234	2	I	100804	010-400-000	N/A	LOAD:ALARM, BULB, BUZZER,	RPR	0006	0.3	35.000	20.500
0001-0024234	2	note			Roof bell doesn't work				**		
0001-0024234	2	note			BELL WAS BENT- OUT OF REACH OF HAMMER - STRAIGHTENED BELL				**		
0001-0024234	2	note			POST				**		
0001-0023250	1	L	101204	015-200-000	N/A	BODY REPAIR/INCIDENTAL	OUT	0002	5.5	31.000	170.500
0001-0023250	1	OP	101204	015-200-000	B'HAM MILLWORK	WOOD	OUT	N/A	1.0	81.150	81.150
0001-0023250	1	note			WOOD WORK REPAIR				**		
0001-0024340	1	P	102204	025-200-000	PMB98CC	KIT-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.000
0001-0024340	1	P	102204	025-200-000	FS1000	FILTER, FUEL USE FOR ORIO	PM	N/A	1.0	8.694	8.694
0001-0024340	1	P	102204	025-200-000	FS1251	FILTER, FUEL TROLLEY	PM	N/A	1.0	7.160	7.160
0001-0024340	1	P	102204	025-200-000	LF3000	FILTER, OIL CUMMINS	PM	N/A	1.0	18.681	18.681
0001-0024340	1	P	102204	025-200-000	OIL SAMPLE	BOTTLE, OIL SAMPLE	PM	N/A	1.0	7.500	7.500
0001-0024340	1	P	102204	025-200-000	3920773	WASHER, SEALING TROLLEY O	PM	N/A	1.0	1.739	1.739
0001-0024340	1	P	102204	025-200-000	5C438	FILTER, HEATER TROLLEY	PM	N/A	1.0	3.336	3.336
0001-0024340	1	P	102204	025-200-000	PMB98CC	END-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.000
0001-0024340	1	P	102204	025-200-000	15W-40L	OIL, LUBEROOM TANK ONLY!!	PM	N/A	25.0	0.786	19.650
0001-0024340	1	L	102204	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0017	8.0	35.000	280.000
0001-0024340	1	L	102204	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0014	3.5	35.000	122.500
0001-0024340	1	L	102204	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0017	0.5	35.000	17.500
0001-0024340	2	I	102204	013-100-000	N/A	WEBASTO HEATER	CHK	0014	1.0	35.000	35.000
0001-0024340	2	note			CHECK WEBASTO WITH TESTER AND BLEED				**		
0001-0024340	5	L	102204	018-000-000	N/A	DOORS & REMOVABLE PANELS	CHK	0014	1.0	35.000	35.000
0001-0024340	5	note			INSTALL REAR DOOR STRUTS - CHECK/TEST REAR DOOR OPENING				**		

DATE: 02/18/2006
 Time: 12:18 p.m.

WHATCOM TRANSPORTATION
 WO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

ID: J-412/ROV PAGE: 33
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WU524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C LfMiles > 244316.0

WO#	LN	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0024340	5	note				PROBLEM - COULDN'T DUPLICATE PROBLEM		**		
0001-0024340	3	L	102204	013-200-000	N/A	HEATER FANS	CHK 0014	0.5	35.000	17.500
0001-0024340	3	note				REPAIR DASH FAN AND TRANS TUBE CLAMP		**		
0001-0024340	4	L	102204	015-150-000	N/A	WIPER BLADES AND WASHER	CHK 0014	0.5	35.000	17.500
0001-0024340	4	note				REPLACE WIPER BLADES		**		
0001-0024340	7	L	102204	017-000-000	N/A	TRANSMISSION SYSTEM	CHK 0014	0.5	35.000	17.500
0001-0024340	7	note				REPAIR TRANS SENDER WIRE AND REPAIR SEAT PAD MOUNT		**		
0001-0024340	8	L	102204	016-000-000	N/A	INTERIOR PANELS & SPECIAL	CHK 0014	1.0	35.000	35.000
0001-0024340	8	note				TIGHTEN ALL WOOD PANELS, AND DRIVER'S REAR MOUNTING PLATE		**		
0001-0024340	5	L	102304	018-000-000	N/A	DOORS & REMOVABLE PANELS	CHK 0014	1.0	35.000	35.000
0001-0024340	5	note				INSTALL REAR DOOR STRUTS - CHECK/TEST REAR DOOR OPENING		**		
0001-0024340	5	note				PROBLEM - COULDN'T DUPLICATE PROBLEM		**		
0001-0024340	6	L	102304	010-360-000	N/A	LIGHTS-INTERIOR	CHK 0014	0.5	35.000	17.500
0001-0024340	6	note				REPLACED LIGHTS		**		
0001-0024340	1	L	102304	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM 0014	1.0	35.000	35.000
0001-0024340	1	P	102504	025-200-000	5C438	FILTER, HEATER TROLLEY	PM N/A	1.0	3.336	3.336
0001-0024340	4	P	102504	015-150-000	5191640	BLADE, WIPER DYNA FOR TRO	CHK N/A	3.0	10.060	30.180
0001-0024340	4	note				REPLACE WIPER BLADES		**		
0001-0024340	5	P	102504	018-000-000	9416K213	SHOCK, COMP. ENGINE (CABLE	CHK N/A	2.0	14.460	28.920
0001-0024340	5	P	102504	018-000-000	9416K83	STUD, BALL 13MM, CABLE CAR	CHK N/A	2.0	1.280	2.560
0001-0024340	5	P	102504	018-000-000	9416K87	SOCKET, METAL BALL (CABLE	CHK N/A	1.0	2.250	2.250
0001-0024340	5	note				INSTALL REAR DOOR STRUTS - CHECK/TEST REAR DOOR OPENING		**		
0001-0024340	5	note				PROBLEM - COULDN'T DUPLICATE PROBLEM		**		
0001-0024340	1	P	102504	025-200-000	53	LAMP	PM N/A	2.0	0.435	0.870
0001-0024462	1	L	102804	023-000-000	N/A	DESTINATION SIGNS	RPR 0015	0.5	35.000	17.500
0001-0024462	1	note				Signs won't scroll out to destinations-sign scrolls stuck		**		
0001-0024462	1	note				LOCATE AND REPLACE BLOWN BREAKER		**		
0001-0024502	1	L	110104	010-000-000	N/A	ELECTRICAL/INSTRMNT SYST	CHK 0006	1.5	35.000	52.500
0001-0024502	1	P	110204	010-000-000	862L-N	TERMINAL, MARINE NEG. EA.	CHK N/A	1.0	0.640	0.640
0001-0024502	1	note				Engine won't start, low batteries.		**		
0001-0024502	1	note				CHARGE, LOAD TEST BATTERIES - OK		**		
0001-0024502	1	note				CHARGING SYSTEM - OK		**		
0001-0024502	1	note				REPLACED BROKEN BATTERY TERMINAL		**		
0001-0024531	1	L	110404	010-650-000	N/A	RADIO/ANTENNA	CHK 0006	0.3	35.000	10.500
0001-0024531	1	note				Radio transmission bad. Hard to understand		**		
0001-0024531	1	note				COULD NOT DUPLICATE		**		

DATE: 02/16/2006
 Time: 12:18 p.m.

WEATCOM TRANSPORTATION
 NO TRANSACTION RPT by VEHICLE
 DATES : 01/01/2003 thru LAST

LC: 3-412/BJV PAGE: 34
 Veh: 0001-808

Year > 1997 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
 Dept > 50 Model > CABLE CAR Lic. Plate > 47630C T.Miles > 244316.0

WO#	LN	TRM	TYP	DATE	VMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/PTY	PRICE/WG	TOTAL COST
0001-0024531	2	L	110404	010-360-000	N/A		LIGHTS-INTERIOR	RPR	0006	0.2	35.000	7.00
0001-0024531	2	note					Front entry light on ceiling is out			**		
0001-0024531	2	note					ALL LIGHTS ARE WORKING			**		
0001-0024534	1	L	110504	018-000-000	N/A		DOORS & REMOVABLE PANELS	RPR	0015	0.5	35.000	17.50
0001-0024534	1	note					You have to wiggle the door control to get the rear door			**		
0001-0024534	1	note					to close			**		
0001-0024534	1	note					REMOVE LEVER ADJUST MICRO SWITCH			**		
0001-0024534	2	L	110504	005-000-000	N/A		BRAKE SYSTEM	CHK	0015	0.5	35.000	17.50
0001-0024534	2	note					Brakes are extremely loud, metal on metal sound			**		
0001-0024534	2	note					INSPECT BRAKES - OK - POWER BRAKE IN REVERSE			**		
0001-0024556	1	L	110804	007-200-000	N/A		EXHAUST SYSTEM	RPR	0017	1.0	35.000	35.00
0001-0024556	1	note					Exhaust to turbo came unclamped.			**		
0001-0024556	1	note					INSTALLED NEW CLAMP			**		
0001-0024556	2	OP	110804	026-000-000	AUTO IDEA		APPRAISAL	OUT	N/A	1.0	150.000	150.00
0001-0024556	2	note					APPRAISAL OF TROLLEY BY AUTO IDEA			**		
0001-0024556	1	P	110804	007-200-000	35416		CLAMP,BAND 3-3/4"	RPR	N/A	1.0	13.600	13.60
0001-0024556	1	note					Exhaust to turbo came unclamped.			**		
0001-0024556	1	note					INSTALLED NEW CLAMP			**		
0001-0024621	1	L	111204	010-400-000	N/A		LOAD:ALARM,BULB,BUZZER,	RPR	0006	0.5	35.000	17.50
0001-0024621	1	note					LH rear vertical bell cord is detached from window frame			**		
0001-0024621	1	note					REPAIR BELL CORD			**		
0001-0024534	3	L	111604	022-000-000	N/A		WHEELCHAIR LIFTS	CHK	0006	0.5	35.000	17.50
0001-0024534	3	note					LIFT WOULD NOT STOW - LIMP LTP - NOT WORKING PROPERLY			**		
0001-0024534	3	note					NO PROBLEM FOUND			**		
0001-0024778	1	L	112904	010-250-000	N/A		HEADLIGHT ASSEMBLY	RPR	0015	0.5	35.000	17.50
0001-0024778	1	P	113004	010-250-000	VF4-15F11		RELAY 30/40A 12V	RPR	N/A	1.0	3.531	3.53
0001-0024778	1	note					No headlights. Touched relays and the came on.			**		
0001-0024778	1	note					LOCATE AND REPLACE H/LAMP RELAY			**		
0001-0024819	1	L	120204	022-000-000	N/A		WHEELCHAIR LIFTS	CHK	0006	0.5	35.000	17.50
0001-0024819	1	note					Ramp out not secure and won't. ??????????????????			**		
0001-0024819	1	note					COULD NOT DUPLICATE			**		
0001-0024819	2	L	120204	010-400-000	N/A		LOAD:ALARM,BULB,BUZZER,	RPR	0006	0.5	35.000	17.50
0001-0024819	2	L	120204	010-400-000	N/A		LOAD:ALARM,BULB,BUZZER,	RPR	0013	1.0	35.000	35.00
0001-0024819	2	note					WCL beeper doesn't operate properly			**		
0001-0024819	2	note					DIAGNOSE, REPLACE BULB IN SIDE WARNING LIGHT			**		
0001-0024819	3	L	120204	010-650-000	N/A		RADIO/ANTENNA	RPR	0013	0.6	35.000	21.00

DATE: 02/16/2006
Time: 12:18 p.m.

WHATCOM TRANSPORTATION
WO TRANSACTION RPT by VEHICLE
DATES : 01/01/2003 thru LAST

ID: 3-412/ROV
Veh: 0001-808

PAGE: 35

Year > 1999 Make > TROLLEY Ser. Num. > 1C9VTE841WH524120 Odom > 244316.0 Shop: ALL
Dept > 50 Model > CABLE CAR Lic. Plate > 47630C L/Miles > 244316.0

WO#	LN	TRN	TYP	DATE	WMRS CODE	PART NUMBER	DESCRIPTION	TYP	MECH	HRS/QTY	PRICE/WG	TOTAL COST
0001-0024819	3	note				Code 13 alarm went off when switch was off				**		
0001-0024819	3	note				REPLACED CODE 13 SWITCH				**		
0001-0024819	4	L	120204	007-000-000	N/A	ENGINE SYSTEM	CHK	0006	0.5	35.000	17.500	17.500
0001-0024819	4	note				OIL LEAK FROM REAR OF BUS				**		
0001-0024819	4	note				FOUND ENGINE OIL FULL CAP OFF - INSTALLED CAP AND CLEANED				**		
0001-0024819	4	note				AREA OF LEAK				**		
0001-0024819	2	P	120304	010-400-000	5592	SWITCH,TOGGLE ON/OFF 2 S RPR	N/A		1.0	2.740	2.740	2.740
0001-0024819	2	note				WCL beeper doesn't operate properly				**		
0001-0024819	2	note				DIAGNOSE, REPLACE BULB IN SIDE WARNING LIGHT				**		
0001-0025232	1	P	011405	025-200-000	PMB98CC	KIT-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.000	0.000
0001-0025232	1	P	011405	025-200-000	FS1000	FILTER,FUEL USE FOR ORIO	PM	N/A	1.0	8.722	8.722	8.722
0001-0025232	1	P	011405	025-200-000	FS1251	FILTER,FUEL TROLLEY	PM	N/A	1.0	7.169	7.169	7.169
0001-0025232	1	P	011405	025-200-000	LE3000	FILTER,OIL CUMMINS	PM	N/A	1.0	18.767	18.767	18.767
0001-0025232	1	P	011405	025-200-000	OIL SAMPLE	BOTTLE,OIL SAMPLE	PM	N/A	1.0	7.468	7.468	7.468
0001-0025232	1	P	011405	025-200-000	3920773	WASHER,SEALING TROLLEY O	PM	N/A	1.0	1.738	1.738	1.738
0001-0025232	1	P	011405	025-200-000	5C438	FILTER,HEATER TROLLY	PM	N/A	1.0	3.336	3.336	3.336
0001-0025232	1	P	011405	025-200-000	PMB98CC	END-CABLE CAR B-1998	PM	N/A	1.0	0.000	0.000	0.000
0001-0025232	1	note				FIRE SUPPRESSION AND FARE BOX TAKEN OUT				**		
0001-0025232	2	P	011405	008-050-000	WF2121	FILTER,EXTEND SERV TIME	CHK	N/A	1.0	39.987	39.987	39.987
0001-0025232	1	P	011405	025-200-000	15W-40L	OIL,LOBEROOM TANK ONLY!!	PM	N/A	25.0	0.790	19.750	19.750
0001-0025232	1	L	011405	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0012	8.0	40.000	320.000	320.000
0001-0025232	1	P	011705	025-200-000	3289056	BELT,SERP. TROLLEY OLD I	PM	N/A	1.0	14.760	14.760	14.760
0001-0025232	1	P	011705	025-200-000	68612	FITT,BRASS PIPE BK PLOG	PM	N/A	1.0	0.316	0.316	0.316
0001-0025232	1	note				FIRE SUPPRESSION AND FARE BOX TAKEN OUT				**		
0001-0025232	2	L	011705	008-050-000	N/A	COOLANT FILTER - ES COMP	CHK	0012	0.5	40.000	20.000	20.000
0001-0025232	3	L	011705	012-100-000	N/A	AIR COMPRESSOR TEST	CHK	0012	0.5	40.000	20.000	20.000
0001-0025232	1	L	011705	025-200-000	N/A	PM B (6,000 & 12,000 MI)	PM	0012	1.0	40.000	40.000	40.000
0001-0025232	1	P	012005	025-200-000	29506478	SWITCH,PRESSURE 2PSI ALL	PM	N/A	1.0	90.860	90.860	90.860
0001-0025232	1	note				FIRE SUPPRESSION AND FARE BOX TAKEN OUT				**		
0001-0025487	1	P	020105	025-000-000	TIRE	TIRE	CHK	N/A	4.0	142.650	570.600	570.600
0001-0025487	1	L	020305	025-000-000	N/A	PREVENTIVE MAINTENANCE	CHK	0012	0.5	40.000	20.000	20.000
0001-0017279	1	L	110708	010-100-000	N/A	BATTERY	OTH	0008	2.0	28.160	56.320	56.320
0001-0017279	1	L	110708	010-100-000	N/A	BATTERY	OTH	0008	2.0	28.160	56.320	56.320
0001-0017383	3	L	111612	018-000-000	N/A	DOORS & REMOVABLE PA	RPR	0014	0.5	28.160	14.080	14.080
0001-0017383	3	L	111612	018-000-000	N/A	DOORS & REMOVABLE PA	RPR	0014	0.5	28.160	14.080	14.080
0001-0017383	3	note				FRONT DOOR INTERLOCK IS NOT ENGAGING PROPERLY,				**		

